

17.09.2020, SI-No. 03/20

Domestic RSO/ND
Abroad: RSO/ND

Service Information

SI-No. 03/20

Exhaust Gas Recirculation Valve (EGR Valve)

Black deposits on the flap


Dear sir or madam,

With this Service Information we would like to inform you about the occasional black deposits on the flap of an EGR Valve.

Note

The black deposit on the flap at the transition to the shaft (see illustration) is a carbon deposit that occurs during laser welding during production. This is normal with these new products and not a reason for complaint.

Illustration: AGR Valve with production-related deposits (Sample A2C59516597)



With kind regards
Product Management
VNI CVS S2 PPM CC1