



LuK Service Info



LuK DMF 415 0560 10

Modified sensor ring

Manufacturer: Ford

Model: Transit

Model year: 2006 -

Engine: 3,2 TDCi

LuK DMF: 415 0560 10



Figure 1: Variant up to 03/2012



Figure 2: Variant starting from 04/2012

As part of the on-going development of our products, the sensor ring and the bearing arrangement of the dual mass flywheel (DMF) 415 0560 10 has been modified.

Figure 1 shows the DMF configuration used in vehicles up to the production date 03/2012. Figure 2 depicts a DMF as installed in vehicles since 04/2012 and also supplied as a spare part since that date.

The new generation sensor ring differs from its predecessor in that it features a reduced material thickness and a different tooth shape. The use of a ball bearing in place of a friction bearing also extends the service life of the DMF.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT