

Service Information XZS102

Wheel Cylinder BWD119

Product improvement BWD119

Following regular field service monitoring it has been identified that it may be possible to disturb the location of the wheel cylinder dust covers when replacing Brake Shoes. Incorrect dustcover location can lead to water ingress into the wheel cylinder resulting in corrosion and premature wear / fluid leakage.

To reduce the possibility of this problem occurring and improve the integrity of the assembly, the wheel cylinder pistons now have grooves with a square section for improved dust cover location (see illustration).

"Note: Following brake shoe or wheel cylinder replacement ensure all components are correctly positioned. Pay particular attention to wheel cylinder dust cover location."











