

FAG Service Info



Take note of different wheel hub designs

Manufacturer:

DAF

Part No. RIU (Repair Insert Unit): 566283.#

Part No. ABS sensor rings: 434 0579 10 434 0580 10



With DAF, two different wheel hubs are used where the wheel bearing unit (RIU) with Part No. 566283.# can be installed.

The two different wheel hubs use different ABS sensor rings, however. When replacing the ABS sensor ring, it is important to identify the visual differences in order to assign the correct ring to the correct hub.



The ABS ring with Part No. 434 0580 10 fits wheel hubs of the old design

Part No. 434 0579 10 fits the wheel hub of the new design

The following table lists the identifying features of the two ABS sensor rings:

Wheel hub	Part No. RIU (Repair Insert Unit)	DAF Part No. ABS-ring	FAG Part No. ABS-ring
old design	566283.#	1805823	434 0580 10
new design	566283.#	1805824	434 0579 10

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264 Fax: +44 (0) 1432 375 760 aftermarket.uk@schaeffler.com www.repxpert.co.uk

