



CLUTCHTECH




TSB - N107

Correct Installation of Release Bearings TB33034 & TB33035


The release bearing in this kit contains two angled tabs, which must be installed on the fork in the correct way to allow the release bearing to pivot on the fork. Installing the bearing backwards will cause the tabs to lock up in the fork and fail when the clutch pedal is operated.

In the correct orientation, the angled tabs should point towards the fork and pivot ball.

INCORRECT FITMENT



CORRECT FITMENT



LEADING BRANDS

CLUTCHPRO CLUTCHPRO COMMERCIAL



For further support, please contact your distributor and/or visit our website.

AU site: australianclutch.com.au
US site: xclutchusa.com

