
















TB2061

SERVICE INFO

LuK Part Nr: 133 0610 10 – 330mm DBVR
332 0014 10 – 330mm TDCN

BELARUS – MTZ80 & MTZ82 SERIES

    <p>LUK 133 0610 10</p> <p>OEM 80-1601130-A 85.1601130-01 85.1601130-02</p>	
   <p>OEM 80.1601090 80.1601090-A</p> <p>LUK 332 0014 10</p>	
   <p>LUK 133 0610 10</p> <p>LUK 332 0014 10</p>	

- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

Phone : +44 (0) 1432 264 264*

Fax : +44 (0) 1432 375 760

E-Mail : hfd-pm@schaeffler.com

www.schaeffler-aftermarket.co.uk

* calls from the UK : 08457 001100



SCHAEFFLER
REP>XPERT