

EUROGUIDE - MAKE MODEL YEAR GUIDELINES

The Euroguide is a document to help identify the right products needed for TPMS maintenance. There are three different coverage lists : a "Make/Model/Year Look up", a "Sensor Look Up" and a "Service Kits Look Up".

Make/Model/Year Look up: This list helps identify the right sensors needed using a Make/Model/Year classification.

1/ Choose the car manufacturer and the model of the car in the column " Make Model".

2/ Identify the code of the car in the second column "Model code".

3/ The columns "Start of Application" and " End of Application" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.

4/ If the car falls within this time range, all the necessary information in the following columns can be found (same line, from left to the right)

5/ **Schrader Part Number:** This is the new After Market reference to order the matching sensor for the car.

6/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.

7/ **Sensor Description :** This is the name and description of the sensor matching with the selected car.

Notice: VDO and HUF are protected brands of the companies VDO and HUF. Schrader is a distributor of VDO and HUF products. Product design, description and brands are properties of HUF and VDO.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk.

This list will be regularly updated.

For further information: tpmseuroshop.com or aftermarket@schradereurope.com

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
Alfa Romeo							
159 Sportwagon	939	2005-07	2013-11	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	185
4C SPIDER	4C	2013-09	2019-06	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3,406
8C SPIDER	920	2007-10	2015-03	99760602100	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	5
Giulia	952	2016-04	2022-12	50547691	4102	Conti Clamp-in TG1C 433MHz Alfa Giulia	55,206
MITO	955	2013-08	2019-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	44,790
MITO	955	2008-06	2013-07	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,515
SPIDER	946	2006-07	2014-05	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	4
Stelvio	949	2017-01	2023-12	50547691	4102	Conti Clamp-in TG1C 433MHz Alfa Giulia	40,503
Alpina							
Alpina 5	F10	2010-10	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	17
Alpina 5	F10	2014-03	2017-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	142
Alpina 5	G30	2017-05	2025-03	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	267
B4 Coupe	F32	2013-12	2021-07	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	506
D3 Kombi	E90	2009-01	2012-12	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	7
D3 Kombi	F30	2013-01	2020-06	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	858
XD3	F25	2014-03	2018-01	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	349
XD3	F25	2013-07	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8
XD3	G01	2018-02	2025-01	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	140
Aston Martin							
CYGNET	630L	2011-04	2014-10	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	17
DB11	VH500	2016-07	2025-06	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,611
DB9 Volante	AM803	2004-04	2018-01	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	568
DBS Vantage	AM803	2007-11	2014-03	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	11
Rapide	VH400	2010-01	2020-11	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	554
VANQUISH Volante	AM310	2012-11	2020-04	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,053
Vantage	VH600	2017-12	2025-06	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,581
VANTAGE Roadster	AM305	2005-07	2018-01	AD43-360671-AA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,971
VIRAGE Volante	AM803	2011-05	2012-12	CD23-360671-CA	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	11
Audi							
A3 Sportback	AU370	2012-11	2020-01	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91,025
A4 Avant	AU491	2015-08	2023-10	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	21,656
A5	AU484	2007-01	2015-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,147
A5	AU494	2016-10	2023-12	5Q0907275B	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29,042
A5 Cabrio	AU494	2017-04	2024-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,779
A5 Cabriolet	AU484	2008-11	2017-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,308
A5 Sportback	AU484	2009-07	2017-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,076
A5 Sportback	AU494	2018-01	2024-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,648
A6	AU581	2018-07	2026-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,284
A6 Allroad	AU561	2006-03	2012-09	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	78
A6 Allroad	AU571	2012-02	2018-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,515
A6 Allroad	AU581	2018-12	2026-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	525
A6 Avant	AU571	2011-01	2019-01	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	114,197
A7	AU583	2018-04	2025-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,923

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NSW)	Sensor Description	Direct TPMS Car Park in market 2018
A7 Sportback	AU573	2010-09	2018-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,970
A8	AU641	2010-01	2018-03	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	16,014
A8	AU651	2017-10	2024-11	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,411
Q2	AU276	2016-07	2024-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	176,557
Q3	AU316	2011-07	2019-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	58,358
Q3	AU326	2018-11	2025-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,708
Q5	AU416	2008-09	2017-08	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25,826
Q5	AU426	2016-09	2023-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29,520
Q7	AU716	2005-11	2014-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,423
Q7	AU716	2014-06	2015-10	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,376
Q8	AU536/3	2018-08	2025-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,168
R8	AU624	2015-10	2024-05	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,851
R8 Spyder	AU714	2007-02	2015-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	773
TT Roadster	AU434	2014-07	2022-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,577
Bentley							
BENTAYGA	BY636	2016-02	2023-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,461
CONTINENTAL Cabriolet	BY614	2006-07	2012-05	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3
CONTINENTAL Cabriolet	BY624	2012-02	2018-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,064
CONTINENTAL Coupe	BY624	2011-01	2018-03	4F0907275B	4009	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	2,818
CONTINENTAL FLYING SPUR	BY611	2005-03	2013-04	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11
CONTINENTAL FLYING SPUR	BY631	2018-09	2026-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	198
Continental GT	BY634	2017-12	2025-09	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,059
FLYING SPUR	BY621	2013-04	2018-10	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,168
MULSANNE	BY731	2010-09	2022-01	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	814
BMW							
1-Series	E80	2004-06	2014-11	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	1,899
1-Series	F20	2017-01	2019-04	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	277,511
1-Series	F20	2011-08	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	233,825
2-Series	F22	2013-11	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	45,700
2-Series	F22	2017-01	2022-09	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	60,931
2-Series Active Tourer	F45	2017-01	2022-05	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	113,414
2-Series Active Tourer	F45	2014-07	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	93,570
2-Series Gran Tourer	F46	2017-01	2022-09	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	58,999
2-Series Gran Tourer	F46	2015-04	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	44,382
3-Series	G20	2018-10	2026-12	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	6,410
3-Series E90	E90	2009-10	2016-12	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	2,944
3-Series F30	F30	2011-11	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	238,857
3-Series F30	F30	2017-01	2019-12	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	229,607
3-Series GT	F34	2017-01	2020-08	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	30,042
3-Series GT	F34	2013-03	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	34,323
4-Series	F32	2017-01	2021-01	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	54,847
4-Series	F32	2013-07	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	57,291
4-Series Gran Coupe	F32	2017-01	2021-07	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	71,377
4-Series Gran Coupe	F32	2014-04	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	57,642
5-Series	F10	2014-03	2017-08	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	162,034
5-Series	F10	2010-01	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	14,120
5-Series	G30	2017-01	2018-02	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	126,139
5-Series	G30	2018-03	2024-10	6887140-01	3057	Schrader Clamp-in Gen Delta 433MHz BMW	109,678
5-Series GT	F07	2014-03	2017-12	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,276
5-Series GT	F07	2009-09	2014-02	36106790054	4010	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	697
6 Gran Coupe	F12	2018-11	2019-12	6887140-01	3057	Schrader Clamp-in Gen Delta 433MHz BMW	287
6 Gran Coupe	F12	2014-03	2018-10	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	9,944
6 Gran Coupe	F12	2012-03	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	487
6-Series	F12	2014-03	2017-12	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,079
6-Series	F12	2018-01	2019-06	36 10 6 890 964	4069	Beru-Huf Clamp-in 433MHz BMW	771
6-Series	F12	2011-01	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	636
6-Series GT	G32	2017-08	2025-01	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	10,449
7-Series	F01	2010-09	2016-01	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	4,258
7-Series	G11	2015-09	2018-02	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	29,697
7-Series	G11	2018-03	2022-10	6887140-01	3057	Schrader Clamp-in Gen Delta 433MHz BMW	8,498
8-Series	G14	2018-09	2026-03	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	595
i3	I01	2017-01	2020-10	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	45,286
i3	I01	2013-09	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	21,220
i8	I12	2017-01	2023-05	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	2,549
i8	I12	2014-05	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	2,825
X1	E84	2014-03	2015-12	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	28,942
X1	E84	2009-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	8,579

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
X1	F48	2015-09	2022-10	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	325,329
X2	F39	2018-01	2025-03	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	37,702
X3	F25	2010-11	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8,265
X3	F25	2014-03	2018-07	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	131,630
X3	G01	2017-11	2018-02	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	11,959
X3	G01	2018-03	2025-03	6887140-01	3057	Schrader Clamp-in Gen Delta 433MHz BMW	46,697
X4	F26	2014-03	2017-12	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	63,852
X4	F26	2018-01	2018-12	36 10 6 890 964	4069	Beru-Huf Clamp-in 433MHz BMW	11,460
X4	G02	2018-06	2025-12	6887140-01	3057	Schrader Clamp-in Gen Delta 433MHz BMW	11,467
X5	E70	2010-03	2014-04	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,130
X5	F15	2017-01	2019-02	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	81,787
X5	F15	2013-09	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	73,293
X6	E71	2011-12	2015-01	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,816
X6	F16	2014-09	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	25,299
X6	F16	2017-01	2020-01	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	30,048
Z4 Roadster	E89	2014-03	2019-02	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,207
Z4 Roadster	E89	2010-09	2014-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	786
Cadillac							
ATS	A1SL	2013-04	2018-12	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	311
CT6	O1SL	2016-08	2018-12	13589601	3063	Schrader Snap-in Faraday 433MHz GM	232
CTS	A1LL	2014-03	2019-06	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	619
CTS	GMX322	2007-11	2014-11	25774007	3055	Schrader Clamp-in Gen J 433MHz GM	41
CTS	GMX226	2011-04	2016-06	20922901	3049	Schrader Snap-in GEN4 type 433MHz GM	28
ESCALADE	GMT926	2006-09	2015-05	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	144
ESCALADE	K2UL	2014-06	2020-11	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	3,537
SRX	GMT166	2010-02	2016-10	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	710
XT4	E2UL	2018-11	2024-12	13516165	3139	Schrader Snap-in Faraday 433MHz GM Basic TFA	14
XT5	C1UL	2018-01	2022-02	13516165	3139	Schrader Snap-in Faraday 433MHz GM Basic TFA	630
XT5	C1UL	2016-08	2017-12	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	861
Chevrolet							
AVEO	G1SC	2010-12	2022-07	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	14,857
AVEO	T250	2006-01	2014-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	107
Camaro	A1BC	2016-01	2022-05	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	3,678
CAMARO Convertible	GMX521	2009-08	2016-10	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	670
Captiva	C100	2006-08	2018-11	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	7,403
COBALT	G1LC	2013-01	2019-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	4,766
CORVETTE Convertible	GMX245	2010-02	2014-05	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	27
CORVETTE Convertible	Y1BC	2014-02	2021-05	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	2,308
CRUZE	D1SC	2008-10	2018-09	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	23,902
EPICA (Clamp-in)	V250	2006-04	2013-07	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	79
EPICA (Snap-in)	V250	2006-04	2013-07	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	79
Express	GMT610	2003-01	2022-03	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	42
LACETTI (Clamp-in)	J200	2003-06	2014-12	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	930
LACETTI (Snap-in)	J200	2003-06	2014-12	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	930
Malibu	E2SC	2017-02	2018-12	13589601	3063	Schrader Snap-in Faraday 433MHz GM	119
Malibu	V300	2014-07	2016-12	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	211
Malibu	V300	2012-01	2014-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	269
NIVA II	2123	2014-06	2023-03	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	113,443
ORLANDO	D1NC	2010-09	2018-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	4,939
Silverado	K2XC	2013-08	2019-03	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	162
Spark	M1JC	2009-07	2019-09	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	7,571
Spark	M200	2005-02	2015-07	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	22
TAHOE (Clamp-in)	GMT921	2006-06	2017-12	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	166
TAHOE (Clamp-in)	K2UC	2014-07	2020-06	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	906
TAHOE (Snap-in)	GMT921	2006-06	2017-12	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	166
TAHOE (Snap-in)	K2UC	2014-07	2020-06	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	906
Trailblazer (Clamp-in)	GM31UX	2013-05	2015-04	20925925	3054	Schrader Clamp-in Gen J 433MHz GM	385
Trailblazer (Snap-in)	GM31UX	2013-05	2015-04	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	385
Traverse	C1YC	2017-12	2023-11	13516165	3139	Schrader Snap-in Faraday 433MHz GM Basic TFA	634
TRAX	G1UC	2012-07	2017-03	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	3,074
TRAX	G1UC	2013-06	2020-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	1,596
VOLT	D1JCI	2011-07	2015-11	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	87
Chrysler							
300C	LX	2012-06	2016-06	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	27
300C	LX	2012-04	2021-04	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	13
DELTA	844	2011-08	2013-07	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	28

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NSW)	Sensor Description	Direct TPMS Car Park in market 2018
GRAND VOYAGER V	RT	2011-01	2015-11	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	145
GRAND VOYAGER V	RT	2011-01					1,182
Pacifica	RU	2017-10	2023-12	53394085	4016	Conti Snap-in TG1D 433MHz Chrysler	112
YPSILON (Direct)	846	2011-08	2017-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	271
Citroen							
Berlingo	B9	2013-10	2016-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHZ PSA	61,893
Berlingo	B9	2013-10					145,039
Berlingo	B9	2008-01	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHZ PSA	5,576
C4 AIRCROSS	J4	2014-06	2017-12	1612477080	4073	Conti Clamp-in TG1C 433MHZ Conti PSA	21,484
C4 Picasso I	B58	2006-05	2015-12	5430W0	3000	Schrader Snap-in GEN4 type 433MHZ PSA	4,678
C5	X7	2007-10	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHZ PSA	2,638
C5	X7	2013-09	2017-11	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHZ PSA	25,347
C6	X6	2005-09	2013-03	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHZ PSA	65
C8	V3	2005-09	2014-07	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHZ PSA	516
C-Elysee	M3/M4	2012-10	2022-06	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHZ PSA	95,070
C-ZERO	S4	2014-06	2018-09	1612477080	4073	Conti Clamp-in TG1C 433MHZ Conti PSA	4,142
Jumper	X2/50	2013-12	2021-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHZ Chrysler/Fiat	164,633
Jumper	X2/50	2006-02	2013-11	5430W0	3000	Schrader Snap-in GEN4 type 433MHZ PSA	2,948
Jumper Combi	X2/50	2014-06	2020-09	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHZ Chrysler/Fiat	16,581
Jumpy	G9	2014-06	2016-12	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	26,513
Jumpy Combi	G9	2014-07	2016-12	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	3,423
Jumpy Combi	G9	2006-09	2014-06	9677130580	3001	Schrader Snap-in GEN4 type 433MHZ PSA HP	857
Nemo	225	2007-11	2015-12	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	12,841
Nemo Multispace	225	2007-10	2018-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	2,716
Dacia							
DOKKER	K67	2014-06	2020-06	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	117,415
Dokker Van	K67	2014-06	2020-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	111,315
DUSTER	H79	2010-02	2015-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	104,658
LODGY	J92	2012-03	2022-03	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	114,705
LOGAN	X90	2014-06	2015-12	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Logan Van	X90	2014-06	2015-12	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	51
Daewoo							
Genra	J200	2004-04	2016-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	19,930
Matiz	M100	2014-01	2018-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	7,134
NEXIA	T	2014-01	2016-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	6,347
Dodge							
AVENGER	JS41D	2007-03	2014-10	56029359AC	3005	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
CALIBER	PM49	2006-04	2012-12	56029359AC	3005	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	5
CHALLENGER Coupe	LC22	2010-02	2014-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	18
DURANGO	WD75	2011-04	2020-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	379
JOURNEY	JC49	2011-01	2014-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	41
JOURNEY	JC49	2014-07	2020-06	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	115
Ram	DS	2013-07	2021-12	68239720AB	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,246
Ram	DS	2009-01	2013-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	98
DS							
DS4	B75	2010-12	2014-01	5430W0	3000	Schrader Snap-in GEN4 type 433MHZ PSA	2,985
DS4	B75	2014-02	2020-08	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHZ PSA	48,778
DS5	B81	2014-02	2018-11	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHZ PSA	25,660
DS5	B81	2011-06	2014-01	5430W0	3000	Schrader Snap-in GEN4 type 433MHZ PSA	2,111
Ferrari							
458 Spider	F142	2009-09	2016-10	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,096
488 Spider	F142M	2015-09	2019-07	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	3,970
599 GTB/GTO	F141	2006-04	2013-02	185189	4001	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	4
CALIFORNIA	F149	2008-12	2017-12	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,727
CALIFORNIA	F149(2)	2018-01	2025-07	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	889
F12 Berlinetta	F152	2012-09	2020-12	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,322
FF	F151	2011-05	2020-03	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,306
Fiat							
124	J12F	2016-04	2023-06	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	17,362
Bravo	198	2007-01	2016-10	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2,234
DOBLO	263	2010-02	2020-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	266,944
DOBLO COMBI	263	2010-01	2019-07	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	3,576
Ducato	X2/50	2014-06	2021-03	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	35,924
DUCATO	X2/44,X2/50	2014-06	2020-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	19
Ducato Combi	X2/50	2014-06	2020-09	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	13,468
Fiorino	225	2007-10	2022-03	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	16,162
Fiorino Qubo	225	2007-10	2022-03	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	4,005

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
FREEMONT	JF	2014-07	2016-06	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	11,664
FREEMONT	JF	2011-03	2014-06	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	3,885
Fullback	4P00	2016-04	2023-06	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	19,886
GRANDE PUNTO	199	2007-09	2014-05	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	915
GRANDE PUNTO	199	2006-01	2014-05	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	18,683
IDEA	350	2003-09	2012-10	51750439	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	98
LINEA	200	2007-03	2015-03	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	15,415
Qubo	225	2008-01	2015-09	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	662
Scudo	G9	2013-11	2017-04	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	19,555
Scudo	G9	2007-01	2013-10	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	981
Scudo Combi	G9	2013-11	2017-04	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	1,899
Scudo Combi	G9	2006-09	2013-10	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	199
SEDICI	YY2	2014-06	2015-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	584
STRADA	178	1999-01	2019-04	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	599
Talento	X82	2016-06	2026-09	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	37,176
Ford							
B-MAX	B232	2014-03	2018-04	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	116,936
ECOSPORT	B515	2014-10	2017-12	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	144,279
ECOSPORT	B515	2018-01	2022-06	F2GT-1A180-CC	3023	Schrader Snap-in Faraday 433MHz Ford	84,634
ECOSPORT	B515	2013-08	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,402
EDGE	CD539	2015-10	2022-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	38,093
EDGE	U387	2007-02	2015-12	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	238
Escape	U377	2007-07	2012-10	9L3Z-1A189-A	3018	Schrader Snap-in GEN4 type 315MHz Ford	1
Explorer	U502	2016-01	2019-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	6,898
Explorer	U502	2011-05	2015-12	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	2,339
F-150	P415	2014-03	2015-06	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	35
F-150	P415	2009-09	2014-02	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	8
F-150	P552	2015-08	2021-04	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	583
Fiesta	B479	2017-05	2023-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	410,319
Fiesta Van	B479	2017-08	2023-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	4,277
FIESTA VI	B299	2014-03	2017-03	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	553,995
FIESTA VI	B299 B479	2017-04	2023-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	169
FIESTA VI Van	B299	2014-03	2017-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	17,203
Focus	C519	2018-09	2019-04	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	79,961
FOCUS III Turnier	C346	2014-03	2020-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	824,151
F-Series	P415	2014-03	2015-06	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	28
F-Series	P415	2009-09	2014-02	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	9
GALAXY	CD340	2006-01	2015-12	8G921A189-KB	4023	Conti Clamp-in TG1B 433MHz Ford	9,674
GALAXY	CD390	2015-05	2026-06	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	55,079
GRAND C-MAX Van	C344	2014-03	2022-12	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	275,401
Ka+	B562	2016-06	2021-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	111,481
KUGA II Van	C520	2014-03	2020-06	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	520,081
Mondeo	CD345	2007-01	2016-01	8G921A189-KB	4023	Conti Clamp-in TG1B 433MHz Ford	16,156
MONDEO V	CD391	2014-10	2017-08	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	154,557
MONDEO V	CD391	2017-09	2025-04	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	74,671
MUSTANG Coupe	S197	2004-12	2015-08	DR3V-1A180-BA	3024	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	192
MUSTANG Coupe	S550	2014-11	2021-10	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	39,210
RANGER	J97U	2006-12	2013-01	6F2Z-1A189A	4055	(blank)	27
RANGER	P375	2014-03	2024-06	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	147,182
S-MAX	CD340	2006-02	2017-03	8G921A159-AE	4021	Conti Clamp-in TG1C 433MHz Ford	14,287
S-MAX	CD389	2015-06	2020-12	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	100,032
NEO CONNECT / GRAND TOURNEO CONNECT	V408	2014-07	2018-02	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	45,058
NEO CONNECT / GRAND TOURNEO CONNECT	V408	2013-09	2014-06	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,038
NEO CONNECT / GRAND TOURNEO CONNECT	V408	2018-03	2022-12	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	13,673
Tourneo Courier	B460	2014-10	2022-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	147,232
Tourneo Courier	B460	2014-04	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,465
TOURNEO CUSTOM	V362	2012-07	2018-12	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	80,264
Transit	V348	2014-03	2015-07	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	1,598
Transit	V363	2014-01	2018-12	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	406,035
Transit	V363	2014-07	2018-12	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	1,588
Transit	V347,V348	2014-03	2014-10	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,379
Transit Combi	V347	2014-03	2014-05	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	6
Transit Combi	V348	2013-06	2014-09	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	245
Transit Combi	V347,V348	2014-03	2014-06	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	362
Transit Connect	V227	2014-03	2015-08	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	865
Transit Connect	V363	2014-04	2018-12	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	28,400
Transit Connect	V408	2014-03	2018-02	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	143,240
Transit Connect	V408	2013-09	2014-03	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,019
Transit Connect	V408	2018-03	2022-12	F2GT-1A180-CB	3023	Schrader Snap-in Faraday 433MHz Ford	48,573
Transit Courier	B460	2014-10	2022-09	EV6T-1A180-CB	3021	Schrader Snap-in Faraday 433MHz Ford	90,649
Transit Courier	B460	2014-04	2014-09	DR3V-1A180-BB	3019	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,692
TRANSIT CUSTOM	V362	2012-07	2018-12	DV6T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford (China)	407,779
Genesis							
G70	IK	2017-12	2026-06	52933-J5000	3131	Schrader Snap-in Faraday 433MHz HKMC	91

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NSW)	Sensor Description	Direct TPMS Car Park in market 2018
G80	DH	2017-09	2020-04	52933-B1100	4060	Conti Clamp-in TG1C 433MHz HKMC	384
G90	HI	2017-04	2023-04	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	515
GMC							
YUKON	GMT922	2006-09	2014-06	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	14
YUKON	KZUG	2014-07	2020-08	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	441
Great Wall							
Hover H2	CH071/CH072	2017-03	2018-10	3641100XKW09A	4092	SATE Clamp-in 433MHz Great Wall FSK	362
HOVER H6	CHB021/CHB022	2013-11	2018-04	3641100XKZ16A	4091	SATE Clamp-in 433MHz Great Wall ASK	2,250
Steed	K5/K6	2018-01	2020-03	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	123
STEED	K2/K4	2014-06	2017-12	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	1,114
Voleex C30	CH041	2014-03	2018-11	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	383
Wingle	K2/K4	2014-06	2016-05	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	328
Wingle	K5/K6	2017-07	2023-10	3641110AK80XA	4083	SATE Clamp-in 433MHz Great Wall	1,126
Honda							
Accord	2GA	2013-04	2019-08	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	929
Accord	QP	2013-04	2016-12	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	1,091
Accord CrossTour	2LX	2018-01	2024-02	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	658
ACCORD VIII	QE	2013-04	2016-02	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	1,155
CROSSTOUR	2NX	2012-01	2016-02	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	30
CROSSTOUR	2NX	2011-04	2015-11	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	328
Jazz	2HQ	2014-03	2015-09	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	487
JAZZ III	2AP	2014-03	2016-07	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	16,386
JAZZ IV	2WF	2015-03	2020-06	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	108,608
Hummer							
HUMMER H3	GMT345	2005-08	2012-11	25789964	3049	Schrader Snap-in GEN4 type 433MHz GM	1
Hyundai							
Accent	HC	2017-04	2023-10	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	10,517
ACCENT IV	RB	2011-03	2018-09	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	54,377
Creta	GS	2016-08	2022-03	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	139,362
Creta (Russia Only)	GS	2016-08	2022-03	52933-C8000	3060	Schrader Snap-in Faraday 433MHz HKMC	15,485
Elantra	AD	2015-06	2021-08	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	37,742
Elantra	MD	2010-11	2017-06	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	13,527
ELANTRA	HD	2006-10	2014-03	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	22
EQUUS	VI	2009-07	2016-04	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	641
GENESIS	DH	2014-02	2020-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	3,243
GENESIS Coupe	BK	2008-09	2017-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	128
GRANDEUR	HG	2014-03	2017-07	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	115
GRANDEUR	HG	2011-06	2014-02	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	67
GRANDEUR	IG	2017-05	2023-09	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	607
H-1	TQ	2014-03	2021-09	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	6,452
H-1 Cargo	TQ	2014-03	2018-09	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	279
H-1 Combi	TQ	2014-03	2014-12	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	5
H-1 Travel	TQ	2014-03	2018-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	3,037
H-1 Van	TQ	2014-03	2018-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	464
H100	TR	2014-03	2018-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	3,231
H100 Van	HR	2004-03	2017-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	4,952
H100 Van	TQ	2014-03	2018-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1,010
i10	PA	2007-10	2017-06	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	5,625
i10	IA	2013-10	2020-05	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	325,657
i20	PB	2008-10	2015-07	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	29,641
i20	GB	2014-10	2021-03	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	411,536
i30	FD	2007-05	2015-04	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	1,344
i30	GD	2012-01	2018-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	179,075
i40	VF	2014-04	2021-09	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	81,419
i40	VF	2011-04	2014-03	52933-3V100	4061	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	4,838
Ioniq	AE	2016-06	2021-06	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	50,079
ix20	JC	2010-09	2018-06	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	105,280
ix35	LM	2011-01	2016-07	52933-2S400	4062	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	1,349
ix35 (Direct)	LM	2015-10	2017-02	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	17,097
ix35 (Direct)	LM	2010-01	2013-10	52933-3M000	4052	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,097
ix35 (High Line)	LM	2013-11	2015-09	52933-2Y450	4051	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	37,741
ix35 (Lo Line)	LM	2013-11	2015-09	52933-2S400	4062	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	37,741
ix55	EN	2007-01	2016-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	139

Make Model Year Look Up

Europe, Ver. 2.0,
Update 10/2018

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
KONA	OS	2017-09	2023-09	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	69,882
NEXO	FE	2018-06	2024-10	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	103
PORTER	HR	2006-01	2017-12	52933-A5100	4060	Conti Clamp-in TG1C 433MHz HKMC	713
Santa Fe	TM	2018-04	2025-03	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	8,992
SANTA FE II	CM	2005-12	2014-10	52933-2B000	4057	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	354
SANTA FE III	DM	2012-06	2019-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	74,779
Solaris	RB	2011-01	2017-03	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	188,129
Solaris	HC	2017-04	2023-03	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	111,423
Sonata	LF	2014-09	2020-03	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	4,643
SONATA VI	YF	2010-03	2015-12	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	46
Tucson	TL	2015-06	2021-09	52933-C1100	3060	Schrader Snap-in Faraday 433MHz HKMC	511,886
VELOSTER	FS	2011-03	2018-02	52933-2V100	3056	Schrader Snap-in GEN4 type 433MHz HKMC	1,304
Infiniti							
EX	P53B	2011-01	2017-09	40700-1LA0E	4094	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	339
FX	P53C	2011-01	2019-09	40700-1LA0E	4094	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	678
G-Series	L53A	2011-01	2014-06	40700-1LA0E	4094	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	105
M	L53E	2009-12	2016-04	40700-1LL0D	4121	Pacific Clamp in Nissan Infiniti 433MHz	171
Q30	GD1A	2016-04	2022-11	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,532
Q30	GD1A	2015-12	2022-09	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	20,542
Q50	L53H	2013-09	2019-09	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	11,286
Q60	D53H	2016-08	2023-06	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	1,288
Q70	L53E	2013-10	2018-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,137
QX50	P53B	2016-01	2018-06	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,517
QX50	P53B	2014-04	2015-12	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	885
QX50	P71A	2018-02	2024-04	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,000
QX56	Z62	2010-07	2012-12	40700-1LL0D	4121	Pacific Clamp in Nissan Infiniti 433MHz	69
QX60	P42J	2014-04	2019-06	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	2,511
QX70	P53C	2016-01	2019-06	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	5,991
QX70	P53C	2013-07	2015-12	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,905
QX80	Z62	2013-11	2014-03	40700-1LL0D	4121	Pacific Clamp in Nissan Infiniti 433MHz	49
QX80	Z62	2014-04	2022-07	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,470
Jaguar							
E-PACE	X540	2017-11	2025-03	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	24,642
F-PACE	X761	2016-01	2023-09	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	78,399
F-TYPE Coupe	X152	2013-02	2020-12	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	16,035
I-PACE	X590	2018-03	2025-09	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	3,911
XE	X760	2015-04	2022-03	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	67,746
XF	X260	2015-09	2024-03	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	43,361
XF SPORTBRAKE	X250	2007-12	2017-09	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	13,982
XJ	X351	2010-01	2020-01	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	6,684
XK Coupe	X150	2014-03	2015-11	C2D21599	4019	Conti Clamp-in TG1C 433MHz Ford	374
XK Coupe	X150	2006-02	2014-02	LR032835	4023	Conti Clamp-in TG1B 433MHz Ford	197
Jeep							
CHEROKEE	KK	2008-01	2014-04	56029359AC	3005	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	71
CHEROKEE	KL	2013-11	2020-09	68249197AA	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	29,940
CHEROKEE	KJ	2001-07	2015-03	56029359AC	3005	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	3
Compass	MK49	2006-09	2017-09	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	3,183
Compass	MP	2017-05	2022-12	53305555	4016	Conti Snap-in TG1D 433MHz Chrysler	63,874
Compass	551	2017-10	2023-08	53305555	4016	Conti Snap-in TG1D 433MHz Chrysler	5,781
GRAND CHEROKEE IV	WK74	2016-04	2020-02	68252495AA	4018	Conti Clamp-in TG1C 433MHz Jeep FCA	30,520
GRAND CHEROKEE IV	WK74	2010-05	2016-03	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	17,924
PATRIOT	MK74	2014-01	2017-11	56029481AB	3005	Schrader Snap-in GEN4 type 433MHz Chrysler	25
PATRIOT	MK74	2007-04	2013-12	56029359AC	3005	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	7
RENEGADE	520	2014-08	2021-12	68105280AF	4016	Conti Snap-in TG1D 433MHz Chrysler	242,339
Wrangler	JK	2010-10	2013-12	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	710
Wrangler	JK	2014-01	2018-12	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	15,141
Wrangler	JL	2018-04	2026-08	68241067AA	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	5,628
Kia							
Cadenza	VG	2011-01	2017-03	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	63
Cadenza	YG	2017-04	2022-06	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	239
CARENS III	UN	2006-08	2012-12	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	31
CARENS IV	RP	2013-01	2019-12	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	69,602
CEE'D	JD	2012-04	2018-04	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	275,915
Cee'd	CD	2018-05	2024-07	52940-J7000	4113	Pacific Clamp-in Fixed Angle ver 1 433MHz Hyundai	31,865
CEE'D	ED	2006-12	2014-05	52933-2L600	4026	Conti Clamp-in TG1B 433MHz HKMC	2,369
Cerato	TD	2009-02	2016-04	52933-3X305	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	922
CERATO	YD	2013-02	2019-06	52933-3X305	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	28,598
K2700	HR	2014-06	2017-06	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
K2700	PU	2014-06	2018-12	52933-4H100	4089	Conti Clamp in TG1C 433MHz HKMC H1 Starex	13,874
Mohave	HM	2008-12	2019-02	52933-2J100	4060	Conti Clamp-in TG1C 433MHz HKMC	2,008
Niro	DE	2016-05	2021-09	52933-F2000	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	76,401
Optima	JF	2015-09	2021-09	52933-D4100	4085	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	66,646
Optima	TF	2010-10	2016-07	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	6,193
Picanto	TA	2011-02	2018-02	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	116,018
Picanto	JA	2017-01	2023-06	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	116,177
QUORIS	KH	2013-02	2019-06	52933-3T000	3061	Schrader Snap-in Faraday 433MHz HKMC	951
Rio (High Line)	UB	2011-06	2017-06	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	27,551
Rio (High Line)	QB	2011-12	2017-12	52933-3V600	4078	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	47,109
Rio (Lo Line)	UB	2011-06	2017-06	52933-3X300	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	110,205
Rio (Lo Line)	QB	2011-12	2017-12	52933-3X305	4053	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	188,434
SORENTO II	XM	2012-10	2015-07	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	8,375
SORENTO II	XM	2009-03	2012-09	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	776
SORENTO III	UM	2014-11	2021-12	52933-2M650	4060	Conti Clamp-in TG1C 433MHz HKMC	78,193
SOUL	AM	2008-09	2013-10	52933-1J000	4027	Conti Clamp-in TG1C 433MHz HKMC	753
SOUL II	PS	2013-11	2019-09	52933-B2100	3059	Schrader Snap-in HS with 20deg angle 433MHz HKMC	77,137
SPORTAGE	SL	2010-06	2014-03	52933-3M000	4052	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	18,706
SPORTAGE	QL	2016-01	2021-12	52933-D9100	4087	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	449,546
SPORTAGE (High Line)	SL	2014-04	2015-12	52933-2Y450	4051	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	31,290
SPORTAGE (Lo Line)	SL	2014-04	2015-12	52933-2S400	4062	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	73,009
Stinger	CK	2017-08	2023-09	52933-J5000	3131	Schrader Snap-in Faraday 433MHz HKMC	6,545
VENGA	YN	2009-11	2018-06	52933-3N100	4060	Conti Clamp-in TG1C 433MHz HKMC	83,609
Lada							
GRANTA	2190	2014-03	2022-03	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	424,014
KALINA	1117-1119	2014-03	2017-05	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	529
KALINA	2192	2013-07	2020-03	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	93,808
VESTA	2180	2015-10	2026-07	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	220,932
Lamborghini							
AVENTADOR Coupe	LB734	2011-06	2020-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,215
GALLARDO	LB614	2003-07	2016-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	54
HURACAN	LB624	2014-06	2022-06	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,133
Urus	LB636	2018-06	2025-11	5Q0907275B	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	516
Lancia							
DELTA III	844	2014-06	2016-12	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	699
DELTA III	844	2008-05	2014-05	51839114	4054	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,339
FLAVIA Cabriolet	JS27	2012-05	2014-11	68078768AA	4015	Conti Clamp-in TG1C 433MHz Chrysler	67
MUSA	848	2004-07	2013-12	51750439	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	692
THEMA	LX	2011-02	2016-06	56029400AD	3008	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	285
VOYAGER	RT	2013-08	2018-09	9673198580/9681102280	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,137
VOYAGER	RT	2011-09	2013-07	56029398AB	3007	Schrader Snap-in GEN4 type 433MHz Chrysler	305
Land Rover							
DEFENDER (Alloy wheels)	L316	1987-03	2019-07	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	19,588
Discovery	L319	2004-07	2017-05	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	28,991
Discovery	L462	2017-01	2025-06	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	36,766
DISCOVERY SPORT	L550	2014-10	2022-09	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	146,857
FREELANDER 2	L359	2006-10	2016-11	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	7,255
Range Rover Evoque	L551	2018-08	2027-03	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	15,535
RANGE ROVER EVOQUE Cabriolet	L538	2011-07	2018-07	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	177,897
RANGE ROVER III	L322	2001-10	2012-12	RQH500470	4023	Conti Clamp-in TG1B 433MHz Ford	330
RANGE ROVER IV	L405	2015-06	2019-12	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	56,345
RANGE ROVER IV	L405	2012-09	2015-05	LR021935	4019	Conti Clamp-in TG1C 433MHz Ford	9,472
RANGE ROVER SPORT	L494	2015-06	2020-09	LR070840	4066	Conti Clamp-in TG1C 433MHz JLR	90,854
RANGE ROVER SPORT	L494	2013-07	2015-05	FW931A159AB	4019	Conti Clamp-in TG1C 433MHz Conti Volvo	14,807
RANGE ROVER SPORT	L320	2010-05	2013-10	FW931A159AB	4019	Conti Clamp-in TG1C 433MHz Conti Volvo	1,139
Range Rover Velar	L560	2017-05	2024-12	C2D47173	4066	Conti Clamp-in TG1C 433MHz JLR	38,899
Lexus							
CT	080A	2011-02	2021-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	32,006
ES	041L	2006-11	2013-02	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
ES (High Line)	980L	2012-09	2018-12	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,399
ES (High Line)	240B	2018-10	2024-12	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	84
ES (Lo Line)	980L	2012-09	2018-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,595
ES (Lo Line)	240B	2018-10	2024-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	337
GS	620N	2005-03	2012-08	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
GS (High Line)	920L	2012-03	2019-09	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,354
GS (Lo Line)	920L	2012-03	2019-09	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,415
GX	837L	2010-03	2023-03	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,796
IS C	030L	2005-10	2013-04	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	135

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
IS III	400A	2013-05	2020-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	22,981
LC (High Line)	950A	2017-07	2025-06	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	192
LC (Lo Line)	950A	2017-07	2025-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	766
LS	250L	2006-10	2012-12	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
LS	200B	2018-02	2025-03	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	1,362
LS (High Line)	250L	2013-01	2018-05	42607-30070	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	140
LS (Lo Line)	250L	2013-01	2018-05	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	561
LX	220L	2013-01	2015-08	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,206
LX	220L	2015-09	2020-09	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	16,321
NX	600A	2014-09	2019-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	86,083
RC	720A	2014-11	2021-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,495
RX	640L	2009-04	2016-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8,922
RX	740A	2015-12	2022-06	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	46,521
Lotus							
ELISE	Monza	2000-09	2020-06	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,354
EVORA	Eagle	2009-06	2022-06	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	753
Exige	Monza	2000-10	2020-12	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,050
Mahindra							
Bolero	CLMM	2014-06	2016-08	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	1
GOA	W105	2015-02	2021-01	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	430
SCORPIO	W105	2015-02	2021-01	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	489
XUV500	W201	2014-06	2021-03	1805BA0131N-A	3062	Schrader Snap-in GEN4 type 433MHz Mahindra	1,339
Maserati							
Ghibli	M157	2013-09	2020-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	13,076
GRAN TURISMO	M145	2010-09	2013-12	282189	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	52
GRAN TURISMO	M145	2014-01	2019-09	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,093
GRANCABRIO	M147	2009-11	2015-06	99760602120	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	147
GRANCABRIO	M147	2015-07	2019-07	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	565
Levante	M161	2016-03	2023-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	14,219
QUATTROPORTE V	M139	2010-01	2013-06	228887	4009	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	6
QUATTROPORTE VI	M156	2013-03	2021-06	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,439
Mazda							
2	J03	2015-02	2021-08	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	29,732
2	J64F	2007-07	2016-06	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	9,871
2	J03W	2015-01	2021-08	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	80,379
3	J68C	2008-11	2017-01	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	3,452
5	J74G	2010-10	2018-01	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	558
6	J61A	2007-12	2012-08	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	821
6	J61A	2012-09	2013-12	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	625
6	J71E	2012-11	2020-12	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	12,246
BT-50	J26E	2012-01	2020-09	BB5T-1A180-AA	3020	Schrader Snap-in GEN4 type 433MHz Ford	24
CX-3	J03K	2015-02	2019-12	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	174,565
CX-5	J53C	2012-01	2017-09	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	158,745
CX-5	J72A	2017-03	2020-04	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	12,440
CX-7	J31H	2006-07	2014-10	GS1D37140	4028	Conti Clamp-in TG1C 433MHz Mazda	46
CX-9	J50C	2007-03	2016-06	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	84
MX-5 III	J04C	2005-12	2015-08	BB337140B	4028	Conti Clamp-in TG1C 433MHz Mazda	255
MX-5 IV	J12A	2015-06	2022-06	BHB637140	4028	Conti Clamp-in TG1C 433MHz Mazda	4,211
McLaren							
MP4 Coupe	P11	2011-03	2018-06	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	513
Sports Series	P13	2015-12	2023-03	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,300
Super Series	P14	2017-07	2025-03	11B0015CP	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	910
Mercedes-Benz							
A-CLASS	W177	2018-06	2026-07	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	89,214
A-CLASS	S176	2012-07	2018-10	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	443,828
AMG GT	C190	2014-10	2022-12	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,621
B-CLASS	W246	2013-01	2019-04	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	255,620
B-CLASS	W246	2011-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,935
C-Class	W204	2013-01	2014-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	13,566
C-Class	W204	2007-01	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,102
C-Class	W205	2014-01	2021-09	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	559,309
C-CLASS Coupe	C204	2011-04	2016-02	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,694
C-CLASS Coupe	C205	2015-11	2023-03	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	105,346
Citan	VS10	2012-09	2019-08	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	71,243
CITAN Combi	VS10	2012-09	2019-08	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	19,027
CLA-Class	C117	2014-12	2019-08	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	228,359
CLA-Class	C117	2013-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10,107
CLC-CLASS	C203	2008-01	2012-05	A0035400217	3011	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler	2

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
CLS	C257	2018-01	2025-04	A0009052102	3057	Schrader Clamp-in Gen Delta 433MHz Daimler	12,069
CLS-Class	C218	2010-12	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,483
CLS-Class	C218	2014-12	2018-05	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	21,416
E-Class	C238	2017-03	2025-04	A0009052102	3057	Schrader Clamp-in Gen Delta 433MHz Daimler	41,160
E-Class	W212	2014-12	2018-03	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	80,127
E-Class	W212	2009-02	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	25,437
E-Class	W213	2016-02	2024-02	A0009052102	3057	Schrader Clamp-in Gen Delta 433MHz Daimler	282,400
E-CLASS Coupe	C207	2012-12	2018-07	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	26,935
E-CLASS Coupe	C207	2009-01	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	994
G-Class	W464	2018-05	2032-06	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,780
G-CLASS Cabrio	G463/461	2014-03	2020-04	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	19,766
GLA-CLASS	X156	2013-12	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,510
GLA-CLASS	X156	2014-12	2020-09	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	244,604
GLC	X253	2015-06	2022-12	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	246,794
GLC Coupe	C253	2016-07	2023-09	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	69,233
GL-CLASS	X164	2009-06	2013-06	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	293
GL-CLASS	X166	2012-10	2017-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17,492
GLE	W166	2015-06	2019-02	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	83,790
GLE	V167	2018-12	2026-02	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	1,140
GLE Coupe	C292	2015-04	2020-03	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	49,773
GLK	X204	2012-12	2016-03	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,632
GLK	X204	2008-08	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,661
GLS	X166	2015-12	2019-08	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	13,394
M-CLASS	W166	2011-10	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,666
M-CLASS	W166	2014-07	2016-12	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	14,542
R-CLASS	V251	2013-01	2015-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	71
R-CLASS	V251	2009-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	122
S-CLASS	W221	2009-07	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	382
S-CLASS	W222	2013-07	2020-12	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	56,491
S-CLASS Coupe	C217	2014-04	2022-10	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,615
SL	R230	2005-01	2012-06	A0025406717	4040	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	3
SL	R231	2014-06	2020-09	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	5,979
SL	R231	2012-01	2014-05	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	553
SLK	R172	2014-12	2018-05	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	9,017
SLK	R172	2013-01	2014-11	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,755
SLK	R172	2011-03	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	732
SLK	R172	2016-02	2021-06	A0009050030	3013	Schrader Clamp-in Gen Gamma 433MHz Daimler	18,964
SLS AMG Roadster	C197	2013-01	2015-02	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	124
SLS AMG Roadster	C197	2010-02	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	45
Sprinter	NCV3	2014-06	2018-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	357,395
Sprinter	VS30	2018-10	2031-12	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	1,714
Sprinter	VS30	2018-04	2031-12	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	61,393
Sprinter	T1N	2013-10	2020-02	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,115
Sprinter (Lo Line)	NCV3	2006-06	2014-05	2E0907508F / 2E0907508J	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	18,885
Sprinter Combi	NCV3	2012-10	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	61
Sprinter Combi	NCV3	2013-01	2018-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	27,961
VARIO	T2N	2014-01	2015-03	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	6
V-CLASS	VS20	2014-03	2024-01	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	122,832
VIANO (Lo Line)	W639	2003-07	2016-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,869
VIANO (Mid-Line)	W639	2003-07	2016-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,869
Vito	VS20	2014-08	2023-10	A4479050500	3012	Schrader Snap-in HS with 10deg angle 433MHz Daimler	205,342
Vito (Lo Line)	W639	2003-05	2015-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	5,249
Vito (Mid-Line)	W639	2003-05	2015-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	5,249
Vito Combi (Lo Line)	W639	2003-05	2015-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,227
Vito Combi (Mid-Line)	W639	2003-05	2015-04	A0025409517	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,227
VITO Tourer	VS20	2014-10	2023-12	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	57,234
X-Class	VS40	2017-09	2026-12	A4709057800	4115	Pacific Snap-In 433MHz Nissan	14,463
Mini							
Countryman	F60	2016-12	2024-01	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	103,332
MINI Cabriolet	F56	2013-12	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	201,850
MINI Cabriolet	F56	2017-01	2023-03	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	279,708
MINI Cabriolet	R56	2006-08	2016-02	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	16,219
MINI CLUBMAN	F54	2017-01	2022-12	36106881890	4043	Conti Clamp-in TG1C 433MHz BMW	59,475
MINI CLUBMAN	F54	2015-09	2016-12	36106856209	4043	Conti Clamp-in TG1C 433MHz BMW	30,338
MINI CLUBMAN	R55	2009-08	2016-01	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,277
MINI CLUBVAN	R55	2013-01	2015-05	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	99
MINI COUNTRYMAN	R60	2014-07	2017-04	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	58,086
MINI COUNTRYMAN	R60	2010-08	2014-06	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	10,564
MINI Coupe	R58	2011-07	2016-05	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,898

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
MINI PACEMAN	R61	2012-11	2014-06	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,355
MINI PACEMAN	R61	2014-07	2017-03	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	6,092
MINI Roadster	R59	2011-12	2014-06	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	738
MINI Roadster	R59	2014-07	2017-02	36106798872	4069	Beru-Huf Clamp-in 433MHz BMW	1,165
Mitsubishi							
ASX	ZC	2014-06	2021-02	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	155,047
Attrage	EL-L	2014-05	2020-04	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1,121
Eclipse Sport	NS	2017-12	2024-03	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	41,681
i-Miev	TQ	2014-06	2019-12	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,638
L200	CR	2014-06	2016-02	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	9,164
L200	4P00	2015-01	2024-09	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	81,126
LANCER VIII Sportback	GS41	2014-06	2019-01	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	8,510
Mirage	EL	2013-02	2020-01	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	5,189
OUTLANDER III	RE	2014-06	2020-06	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	198,270
PAJERO IV	BK	2014-07	2025-09	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	28,391
PAJERO SPORT II	CR45	2014-06	2016-06	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	4,926
PAJERO SPORT III	4P45	2016-05	2024-06	4250C275	4079	Conti Snap-in TG1D 433MHz Conti Mitsubishi	12,359
Spacestar	EL	2014-06	2020-04	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	97,760
Nissan							
370 Z Coupe	C53D	2010-11	2014-07	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	122
370 Z Roadster	RC53D	2014-08	2018-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	524
Almera	LB1A	2013-05	2020-04	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	70,638
Atleon	F24	2014-10	2019-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	14
Cabstar	F24	2014-10	2020-03	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	23,281
Cabstar E	F24	2014-10	2020-03	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	167
CUBE	X12B	2009-10	2014-09	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4
Frontier	D22	2005-10	2015-03	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2
GT-R	D52E	2010-11	2013-11	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	60
GT-R	D52E	2013-12	2019-06	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,545
JUKE	P12C	2015-10	2019-09	40700-5ZHOA	4115	Pacific Snap-In 433Mhz Nissan	289,621
JUKE	P12C	2010-08	2015-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	88,526
LEAF	B12G	2010-11	2015-09	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	10,757
LEAF	B12G	2017-01	2018-05	40700-5ZH0A	4115	Pacific Snap-In 433Mhz Nissan	18,993
LEAF	B12P	2018-01	2021-12	40700-5ZB1B	4034	Conti Snap-in TG1D 433MHz Renault	22,174
Micra	B02E	2017-02	2023-06	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	184,653
MICRA IV	B02A	2010-07	2019-06	40700-3HN0B	4077	Pacific Clamp-in Fixed Angle 433MHz Nissan	126,377
Murano	P42M	2015-01	2021-07	40700-6WY0A	4047	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	6,665
Murano (Russia Only)	P42M	2015-01	2021-07	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	3
MURANO II	P42D	2008-04	2014-09	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,385
Navara	H60A	2017-01	2023-12	40700-5ZHOA	4115	Pacific Snap-In 433Mhz Nissan	58,794
Navara	H60A	2015-12	2016-12	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	23,665
NOTE	J02C	2013-09	2017-12	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	84,157
NOTE	L11E	2004-09	2014-10	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	3,355
NP300	D22	1999-01	2018-02	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	952
NP300	H61B	2009-01	2015-10	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	9
NP300 NAVARA	H61B	2005-07	2016-11	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	12,807
NP300 NAVARA Pick-up	H60A	2016-05	2024-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1,891
NT500	F91G	2014-02	2017-03	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1,673
NV200	X11M	2009-09	2019-09	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	59,352
NV200 / EVALIA Bus	X11M	2012-01	2019-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	188
NV200 Combi	X11M	2009-11	2020-03	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	21,299
NV300	X82	2016-10	2026-09	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	14,299
NV300 Combi	X82	2016-09	2026-06	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,480
NV400	X62	2014-06	2020-12	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	24,153
NV400 Combi	X62	2014-06	2020-12	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	984
PATHFINDER III	P61B	2005-01	2015-12	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,854
PATHFINDER IV	P42K	2014-03	2019-12	407003JA0A	4071	Conti Clamp-in TG1C 433MHz Conti Nissan	3,487
PATROL VI	Y62	2014-06	2023-03	40700-3HN0B	4077	Pacific Clamp-in Fixed Angle 433MHz Nissan	1,052
PATROL VI	Y62	2010-02	2014-05	40700-1LL0D	4121	Pacific Clamp-in Nissan Infiniti 433MHz	136
PIXO	YC5	2009-05	2015-06	40700JY00B	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	532
Pulsar	B12L	2014-07	2018-12	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	96,885
QASHQAI II	F32S	2016-10	2021-07	407004CB0A	4034	Conti Snap-In TG1D 433MHz Renault	623,055

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
QASHQAI II	P32S	2014-01	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	366,880
Sentra	L12F	2013-11	2017-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	7,365
TEANA III	L42L	2014-03	2018-11	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	4,198
TERRANO	H79N	2014-06	2019-10	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	46,613
Tiida	B12D	2012-08	2013-10	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	262
Tiida	B12L	2015-03	2015-11	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	1,574
X-TRAIL	P32R	2013-12	2016-09	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	92,292
X-TRAIL	P32R	2016-10	2021-03	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	194,905
Opel							
ADAM	GM 4403	2013-01	2014-07	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	6,635
ADAM	GM 4403	2014-08	2020-12	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	140,787
AGILA	H0310	2014-06	2015-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	2,104
AMPERA	D1JOI	2011-09	2015-12	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	535
Ampera-e	G2KCZ	2017-01	2023-09	13589601	3063	Schrader Snap-in Faraday 433MHz GM	3,521
ANTARA	C105	2010-11	2015-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	7,276
ANTARA	C105	2016-01	2017-06	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	1,433
ASTRA H	GM A3300	2011-07	2016-04	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	4,600
ASTRA H	GM A3300	2004-07	2014-01	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	42
ASTRA J	GM P3400	2014-06	2018-06	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	192,672
ASTRA J	GM P3400	2011-09	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	31,640
ASTRA K	D2JO	2015-09	2022-09	13594222	3071	Schrader Snap-in Faraday 433MHz GM	477,479
ASTRA K	D2JO	2016-01	2021-12	13594222	3071	Schrader Snap-in Faraday 433MHz GM	720
ASTRA K Van	GM P3400	2014-06	2016-06	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	240
CASCADA	D1AO	2013-01	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	675
CASCADA	D1AO	2014-06	2022-06	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	12,144
Combo	263	2012-01	2018-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	44,672
Combo Combi	263	2011-11	2018-06	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	6,555
Corsa	GM 4530	2014-12	2019-12	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	631,042
CORSA D	GM S4400	2014-06	2014-10	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	446
CORSA D Van	GM S4400	2014-06	2014-10	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	22,142
CORSA E	GM 4530	2014-11	2019-12	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	11,298
Insignia	GM G3700	2014-05	2017-11	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	112,144
Insignia	GM G3700	2011-09	2014-04	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,300
Insignia	E2JO	2017-04	2023-12	13597645	3025	Schrader Snap-in Faraday 433MHz GM	111,743
Karl	M2JO	2015-02	2022-07	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	124,766
MERIVA B	GM S4470	2010-04	2017-09	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	95,149
MOKKA	G1UO	2012-07	2015-08	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	80,558
MOKKA	G1UO	2015-09	2020-03	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	383,624
Movano	X62	2014-06	2020-09	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	57,189
Movano Combi	X62	2014-06	2020-09	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	2,731
Vivaro	X82	2014-10	2020-02	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	101,988
Vivaro Combi	X82	2014-10	2020-02	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	44,905
Zafira	GM P3470	2015-02	2021-12	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	1,057
ZAFIRA B	GM A3370	2011-07	2015-10	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	6,546
ZAFIRA TOURER C	GM P3470	2011-11	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,416
ZAFIRA TOURER C	GM P3470	2014-06	2022-06	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	128,547
Peugeot							
207 SW	A7	2005-11	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	6,481
207 SW	A7	2013-09	2016-03	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	4,953
207 Van	A7	2005-11	2014-09	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	322
3008	T84	2008-11	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	7,148
3008	T84	2013-09	2017-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	90,539
301	M3/M4	2012-10	2022-03	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	61,490
308	T7	2007-07	2013-12	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	276
308 SW	T7	2013-09	2016-03	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	4,100
308 SW	T7	2007-05	2013-08	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	7,709

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
4008	J3	2014-06	2018-01	1612477080	4073	Conti Clamp-in TG1C 433MHz Conti PSA	4,546
408	T73	2012-07	2019-03	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	7,387
5008	T87	2009-09	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	3,649
5008	T87	2013-09	2017-04	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	51,120
508 SW	W2	2010-09	2013-09	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	5,641
508 SW	W2	2013-09	2017-06	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	80,270
807	V2	2004-10	2015-06	5430T4	4031	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	743
Boxer	X2/50	2013-12	2020-12	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	201,624
Boxer Combi	X2/50	2014-06	2021-03	05154876AA	3009	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,021
EXPERT	G9	2014-06	2016-09	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	21,750
EXPERT	G9	2006-10	2013-12	9677130580	3001	Schrader Snap-in GEN4 type 433MHz PSA HP	1,752
EXPERT Tepee	G9	2014-06	2017-06	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	4,754
ION	S3	2014-06	2018-11	4250C477	4073	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5,161
PARTNER	B9	2014-06	2019-09	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	293,734
PARTNER Tepee	B9	2014-06	2019-09	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	83,193
RCZ	T75	2009-12	2013-09	5430W0	3000	Schrader Snap-in GEN4 type 433MHz PSA	666
RCZ	T75	2013-10	2016-12	9811536380	3002	Schrader Snap-in HS with 20deg angle 433MHz PSA	4,209
Porsche							
911	997	2008-04	2013-01	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26
911	PO674	2016-09	2020-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	36,199
911	PO674	2011-09	2016-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	21,645
918 Spyder	PO715	2014-05	2015-09	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	109
BOXSTER	987	2008-11	2012-12	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32
BOXSTER Spyder	981	2016-09	2020-09	9A790727502	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,059
BOXSTER Spyder	981	2012-04	2016-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	7,408
CAYENNE	PO536	2017-10	2025-04	9A790727502	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	22,911
CAYENNE	PO526	2014-09	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	43,063
CAYENNE	PO526	2010-04	2014-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,169
CAYMAN	981	2013-04	2016-08	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,037
CAYMAN	981	2016-09	2020-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,999
CAYMAN	987	2009-02	2013-03	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	43
MACAN	PO416	2014-02	2021-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	96,053
PANAMERA	PO623	2016-10	2024-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25,375
PANAMERA	PO613	2013-10	2017-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,162
PANAMERA	PO613	2009-06	2013-09	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	552
Qoros							
3	CF11	2017-09	2021-12	42753-TL0-G520	4072	Conti Clamp-in TG1C 433MHz Conti Honda	16
Ram							
1500	DT	2018-06	2024-12	68293199AA	3066	Schrader Snap-in Gen6 PAL Potted 433MHz Chrysler	389
1500 Standard Cab Pickup	DS	2012-01	2017-12	68239720AB	4068	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	1,861
Renault							
Alaskan	U60A	2017-06	2026-06	40700-5ZH0A	4115	Pacific Snap-In 433MHz Nissan	8,199
Captur	J87	2013-02	2015-12	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	160,212
Clio	X85	2005-05	2014-10	820253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	8,290
CLIO Grandtour	X85	2007-03	2013-10	820253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	1,044
CLIO IV	X98	2014-06	2015-12	407009987R	3073	Schrader Snap-in Faraday 433MHz Renault T4	242,907
CLIO IV	X98	2012-08	2019-06	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	137,599
DOKKER	F67,K67	2014-06	2018-12	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	522
ESPACE IV	J81	2002-08	2015-10	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	609
ESPACE IV	J81	2002-08	2016-02	8200023746	3042	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	2,241
ESPACE V	JFC	2015-04	2021-03	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	64,875
FLUENCE	L38	2009-11	2017-10	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	61,570

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
KADJAR	HFE	2015-04	2021-06	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	369,886
KANGOO / GRAND KANGOO	X61	2007-12	2019-07	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	176,439
Kangoo Passenger	X61	2007-10	2019-08	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	39,495
KOLEOS	H45	2014-01	2017-06	407003VU0A	4032	Conti Clamp-in TG1C 433MHz Renault	5,693
KOLEOS	H45	2008-02	2013-12	407001AY0A	3039	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,244
KOLEOS	HZG	2016-10	2022-06	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	35,185
Laguna Coupe	D91	2008-08	2015-11	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	893
LAGUNA III Grandtour	X91	2007-06	2016-12	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	9,341
LATITUDE	L43	2010-09	2016-08	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	931
LOGGY	J92	2012-12	2022-03	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	639
LOGAN II	X52	2014-07	2015-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,195
MASTER III	X62	2014-03	2020-12	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	308,940
MASTER Passenger	X62	2014-03	2021-02	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,459
Megane	B32	2009-11	2016-04	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4,531
Megane	B32_X95	2009-03	2017-01	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,830
Megane	LFF	2016-09	2024-09	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	101,165
Megane	XFB	2015-11	2023-09	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	436,407
MEGANE	X95	2008-10	2017-01	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	136,780
MEGANE VAN	X95	2008-10	2016-10	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	5,155
MEGANE VAN	XFB	2016-02	2023-06	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	14,561
MODUS / GRAND MODUS	J77	2008-02	2012-07	8200253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	9
MODUS / GRAND MODUS	J77	2004-05	2014-12	8200253215	3040	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	1,469
SANDERO/STEPWAY II	B52	2014-07	2015-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	19,849
Scenic	J95	2009-04	2017-05	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	147,473
Scenic	JFA	2016-09	2023-06	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	213,623
TALISMAN	XFD	2015-09	2022-09	407004CB0A	4034	Conti Snap-in TG1D 433MHz Renault	92,317
Trafic	X82	2014-04	2026-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	270,727
Trafic	X83	2014-03	2015-01	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,566
TRAFIC Passenger	X82	2014-04	2026-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	59,103
TRAFIC Passenger	X83	2014-03	2016-02	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	740
TWINGO II	X44	2014-03	2016-12	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,380
TWINGO III	X07	2014-06	2025-04	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	295,853
TWINGO VAN	X07	2014-08	2025-01	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,166
WIND	X33	2010-06	2014-06	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	90
Zoe	X10	2012-09	2022-12	407000435R	4035	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	96,385
Rolls-Royce							
CULLINAN	RR31	2018-05	2026-04	A0009054104	3057	Beru-Huf Clamp-in 433MHz BMW / Mercedes	167
Dawn	RR06	2016-02	2022-03	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	685
GHOST	RR04	2010-09	2020-02	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	887

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
PHANTOM	RR01	2012-01	2017-07	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	96
PHANTOM	RR11	2017-09	2028-06	36106872774	3057	Schrader Clamp-in Gen Delta 433MHz BMW	146
PHANTOM Drophead Coupe	RR02	2007-08	2017-01	36236798726	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	102
WRAITH	RR05	2013-08	2021-03	36106856227	4010	Beru-Huf Clamp-in Separate valve G3.4 433MHz BMW	1,031
Saab							
9-3X	SB440	2007-07	2014-04	B121G600F	3058	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	104
9-5	SB650	2010-06	2012-12	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13
SEAT							
EXEO ST	SE411	2013-06	2015-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	24
Skoda							
CITIGO	SK120	2011-12	2020-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	139,095
FABIA III Kombi	SK260	2014-10	2021-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	61,232
FABIA VAN	SK260	2014-11	2021-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	276
Kodiaq	SK326/1	2016-10	2023-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14,192
OCTAVIA	SK371	2013-02	2020-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	97,470
OCTAVIA	SK351	2014-06	2016-08	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
RAPID	SK351/3	2012-09	2019-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,948
Rapid Spaceback	SK350/3	2013-08	2019-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,522
SUPERB	SK461	2008-04	2016-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,465
SUPERB	SK481	2015-05	2022-08	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	27,616
YETI	SK316	2009-06	2018-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,667
Smart							
forfour	W454	2004-01	2015-02	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10
FORFOUR	W453	2014-09	2025-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	123,034
FORTWO	A451	2013-01	2016-04	A0009057200	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	15,843
FORTWO	A451	2007-01	2012-12	A0009054100	3011	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,850
FORTWO Coupe	C453	2014-09	2025-09	407009322R--D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	219,151
Ssangyong							
ACTYON I	C100	2014-03	2017-02	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	124
Actyon Sports	Q150	2014-03	2018-06	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	401
ACTYON SPORTS II	Q150	2014-11	2018-06	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,482
Actyon SUT	Q150	2014-03	2018-06	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	697
Actyon SUT	Q200	2018-07	2024-12	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	59
KORANDO	C200/AS11	2014-06	2018-12	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4,876
KORANDO	C200/AS11	2013-07	2020-07	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	467
KORANDO	C200/AS11	2013-08	2019-09	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	12
KORANDO C	C200/AS11	2013-08	2019-12	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14,403
Korando Sports	Q200	2018-07	2025-02	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	478
KYRON	D100	2014-06	2016-09	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2,400
REXTON	Y200	2014-05	2018-12	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,434
REXTON	Y400	2017-09	2024-08	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	4,756
RODIUS	A100	2014-05	2018-12	41990-34000	3068	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	7,450
TIVOLI	X100	2015-03	2022-03	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	26,745
Tivoli XLV	X105	2016-04	2022-06	41990-35000	4084	Huf Snap-in 433MHz Huf Ssangyong	6,757
Subaru							
BRZ	E88	2012-05	2021-07	SU003 05268	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,827
FORESTER	FM5	2014-01	2019-06	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	66,801
FORESTER	PF3	2014-01	2014-12	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
FORESTER	ES1	2018-10	2023-12	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	450
Impreza	MF1	2014-01	2017-03	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,654
Impreza	HR3	2017-01	2022-03	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	3,152
IMPREZA	ZR1	2014-01	2015-12	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	90
LEGACY	EZ5	2014-01	2015-12	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	495
LEVORG	VL9	2015-06	2021-03	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10,559
OUTBACK	BF4	2014-09	2020-09	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	749
OUTBACK	BF4	2018-01	2020-09	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	8,470
OUTBACK	BF4	2014-08	2017-12	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	23,802
OUTBACK	EZ5	2014-03	2015-08	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,111
TREZIA	217A	2014-01	2017-01	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	115

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
TRIBECA	00X	2014-01	2015-06	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
TRIBECA	TR8	2018-11	2024-09	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	128
WRX	VL9	2014-03	2018-12	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,970
XV	MF1	2014-01	2017-09	28103FJ000	3064	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25,999
XV	HQ4	2017-08	2022-09	28103FL000/FL00A	3076	Schrader Snap-in Faraday 433MHz Subaru	21,978
Suzuki							
ALIVIO	YL1	2018-09	2021-04	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	136
ALTO	YC5	2014-06	2016-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	6,497
Baleno	YR	2015-12	2022-04	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	48,032
CELERIO	YLA	2014-09	2020-09	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	81,236
GRAND VITARA II	YT4	2014-06	2020-09	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	9,701
Ignis	YJ	2016-07	2022-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	86,231
Jimny	YR7	2014-06	2018-10	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	44,586
Jimny	YR7(2)	2018-08	2025-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	6,708
Jimny	YR6	2014-06	2018-08	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	3,216
Jimny Wide	YR7(2)	2018-11	2025-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	148
KIZASHI	YW1	2014-06	2016-06	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	66
SPLASH	YV1	2014-06	2016-11	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	3,266
Swift	YP6,YP7	2014-06	2017-05	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	65,711
Swift	YS	2017-02	2023-06	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	76,926
SWIFT IV	YP6	2014-06	2017-06	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	18,067
SX4	YY1	2014-06	2015-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	694
SX4	YY1,YY3	2014-06	2015-12	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	2,264
SX4 S-Cross	YAA	2014-09	2020-03	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	2,713
SX4 S-Cross	YAA	2013-09	2020-06	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	117,626
VITARA	YFA	2015-02	2021-04	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	260,578
Tesla							
Model 3	Model E	2018-01	2028-06	1034602-00-A	4081	Conti Clamp-in TG1C 433MHz Tesla	2,606
MODEL S	Model S	2014-09	2020-02	1034602-00-A	4081	Conti Clamp-in TG1C 433MHz Tesla	53,202
MODEL S	Model S	2013-01	2014-08	FS1511	4058	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	1,510
MODEL X	Model X	2016-05	2023-08	1034602-00-A	4081	Conti Clamp-in TG1C 433MHz Tesla	30,078
ROADSTER	DarkStar	2008-03	2012-07	2000680	4009	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	5
Toyota							
Alphard	480L	2012-02	2015-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	112
Alphard	580A	2015-07	2021-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,391
AURIS TOURING SPORTS	130A	2012-12	2019-04	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	454,391
AVENSIS	446L	2008-12	2018-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	103,548
Aygo	200A/201A	2014-07	2022-08	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	299,247
Camry	050A	2017-09	2020-06	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	42,752
CAMRY	050A	2012-01	2017-08	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	80,131
C-HR	560A	2016-11	2023-03	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	248,926
Corolla	150B	2018-12	2023-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,274

Make Model Year Look Up

Europe, Ver. 2.0,
Update 10/2018

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
Corolla	133L_252L	2007-10	2014-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	120
Corolla	150L	2007-01	2016-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,332
COROLLA	079L_140N_340N	2002-01	2018-06	42607-42020	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
COROLLA	150A	2014-08	2019-03	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,794
COROLLA	466A	2013-07	2018-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	171,611
COROLLA	252L	2007-07	2014-07	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	6,316
Dyna	131N	2012-01	2021-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,071
FJ CRUISER	155L	2006-05	2018-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8
Fortuner	669L	2014-07	2017-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	568
GT 86 Coupe	E88	2012-04	2021-06	SU003 05268	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	6,266
HIACE	550N	2005-01	2019-03	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,216
HIACE Combi	550N	2004-08	2017-09	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
HIGHLANDER	440A	2014-04	2020-09	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,774
Hilux	669L	2009-01	2017-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	38,800
HILUX VIII Pick-up	640A	2015-07	2023-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	97,931
IQ	630L	2008-11	2016-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,433
Land Cruiser	611L	2009-09	2017-07	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12,827
Land Cruiser	611L	2017-08	2022-03	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	8,113
LAND CRUISER 200	215L	2007-11	2017-08	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	834
LAND CRUISER 200	215L	2012-01	2015-08	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12,314
LAND CRUISER 200	215L	2015-09	2020-12	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	52,728
LAND CRUISER 200	215L	2017-08	2020-06	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	4
Land Cruiser Prado	611L	2009-11	2017-07	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,097
Land Cruiser Prado	611L	2017-08	2023-12	42607-48020	4114	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	20,446
MIRAI	470A	2017-12	2019-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	119
Previa	085L	2007-01	2020-09	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius	590L	2009-06	2016-10	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	9,577
Prius	690A	2015-11	2021-06	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,787
Prius Plus	030A	2012-04	2018-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	23,599
PROACE	G9	2014-06	2016-08	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	7,150
PROACE	K0	2016-06	2025-06	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	34,842
PROACE Combi	G9	2014-06	2016-09	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	68
PROACE Combi	K0	2016-08	2025-03	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	1,231
Proace Verso	K0	2016-06	2025-06	9808859080	3003	Schrader Snap-in HS with 20deg angle 433MHz PSA HP	9,778
RAV 4 III	120L	2005-11	2014-03	42607-50010	4044	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,269
RAV 4 IV	410A	2013-02	2019-04	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	372,770
Sequoia	200L	2008-02	2021-12	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	29
Sienna	580L	2010-06	2021-04	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	296
TUNDRA	480A/180L	2007-04	2022-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	153
URBAN CRUISER	260L	2008-12	2016-07	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	292
VENZA	470L	2009-04	2017-05	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,623
VERSO	595L	2009-02	2018-07	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	88,877
VERSO S	770L	2011-01	2017-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,730
YARIS	850L	2011-08	2021-01	42607-02031	4045	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	748,452
Volkswagen							
AMAROK	VN417	2009-11	2018-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	63,281
AMAROK	VN417	2018-03	2024-03	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	5,413
Arteon	VW483	2017-05	2024-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,790
BEETLE	VW325	2012-12	2020-07	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,282

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
Caravelle	VN750	2003-04	2016-08	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,039
CC	VW464	2012-01	2017-07	3AA907275B	4011	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	1,207
Crafter	VN830	2014-02	2017-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	20,380
Crafter	VN54T	2018-03	2027-07	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	39,359
Crafter (Lo Line)	VN830	2006-04	2014-01	2E0907508F / 2E0907508J	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	1,254
Crafter Combi	VN830	2006-04	2014-01	2E0907508F / 2E0907508J	4038	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	39
Crafter Combi	VN830	2014-02	2017-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	683
Crafter Combi	VN54T	2018-03	2027-04	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	1,010
EOS	VW465	2006-02	2016-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	667
GOLF PLUS	VW369	2008-12	2014-01	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,872
GOLF SPORTSVAN	VW379	2014-03	2021-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	60,857
GOLF SPORTSVAN	VW379	2014-07	2021-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,212
GOLF VI	VW360	2008-09	2021-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,581
GOLF VI	VW362	2009-09	2014-10	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,501
GOLF VII	VW370	2012-09	2020-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,867,791
Jetta	VW371	2018-06	2025-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,584
JETTA IV	VW361	2010-11	2018-11	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	34,732
Multivan	VN750	2004-03	2015-10	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	173
NEW BEETLE	VW324	2011-09	2020-03	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,541
PASSAT	VW471	2010-10	2014-07	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	11,609
PASSAT	VW471	2014-08	2015-09	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,085
PASSAT	VW481	2014-10	2021-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	229,272
Passat CC	VW464	2008-03	2017-07	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,214
PHAETON	VW611	2007-06	2016-09	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,590
Polo	VW270	2017-09	2024-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	123,395
SCIROCCO	VW364	2008-06	2018-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,957
SHARAN	VW428	2010-07	2023-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	34,431
TIGUAN	VW316	2007-08	2016-12	3AA907275D	4011	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	57,713
TIGUAN	VW326	2016-01	2024-11	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	203,578
TOUAREG	VW526	2014-08	2018-07	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,887
TOUAREG	VW526	2010-04	2014-07	7PP907275F	4009	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,791
TOUAREG	VW536	2018-09	2025-02	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,567
TOURAN	VW368	2015-01	2016-12	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,433
TOURAN	VW378	2015-09	2022-06	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	95,384
Transporter	VN750	2003-04	2016-01	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,796
Transporter	VN46T	2018-03	2024-10	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	96,753
Transporter Shuttle	VN750	2004-03	2016-04	5Q0907275	4012	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	528
Transporter Shuttle	VN46T	2018-03	2024-06	2N0907251	3108	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	1,854
Volvo							
C30	Y279	2006-09	2014-03	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	563
C70 II Cabriolet	Y281	2006-03	2015-12	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	258
S40 II	Y276	2003-12	2014-05	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	327
S60	V431	2018-12	2024-10	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	298
S60 Cross Country	V431	2018-12	2024-10	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	16
S70	Y555	2014-07	2020-12	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	53,757
S90	V541	2016-05	2024-03	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	26,235

Car Make	Car Model Code	Start of application	End of application	OE sensor reference	Schrader Part Number (NEW)	Sensor Description	Direct TPMS Car Park in market 2018
V40	Y555	2014-07	2020-09	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	208,919
V50	Y280	2003-11	2014-01	30681555	4023	Conti Clamp-in TG1B 433MHz Ford	1,086
V60	V432	2018-08	2024-10	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	12,949
V60	Y352	2014-07	2017-09	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	77,654
V60	Y352	2015-05	2018-08	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	27,248
V60 Cross Country	V432	2018-10	2024-09	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	3,275
V70 III	Y285	2014-07	2016-12	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	33,522
V90 Cross Country	V542	2016-12	2022-09	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	23,546
XC60	Y413	2014-07	2016-09	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	108,932
XC70 II	Y285	2014-07	2017-12	31445473	4070	Conti Clamp-in TG1C 433MHz Volvo	26,880
XC90 I	Y289	2002-04	2015-05	30748354	3046	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	3,031
XC90 II	V526	2015-01	2016-03	31362304	3069	Schrader Snap-in HS with 20deg angle 433MHz Volvo	21,654
Karma							
KARMA	K1	2011-06	2014-01	C131124501000	4086	Lear Snap-in Fixed Angle ver 1 433MHz Fisker sensor	21
Vauxhall							
ADAM	GM 4403	2013-01	2014-07	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	2,081
ADAM	GM 4403	2014-08	2020-05	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	29,373
AGILA	H0310	2014-06	2015-09	43139-61M00	4065	Conti Clamp-in TG1C 433MHz Suzuki	614
AMPERA	D1JOI	2012-01	2015-12	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	206
ANTARA	C105	2010-11	2015-12	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	2,645
ANTARA	C105	2016-01	2017-04	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	704
ASTRA Mk VI	GM P3400	2014-06	2016-04	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	34,996
ASTRA Mk VI	GM P3400	2011-09	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,876
ASTRA Mk VII	D2JO	2015-10	2022-04	13594222	3071	Schrader Snap-in Faraday 433MHz GM	135,940
Astra Van	GM A3300	2006-10	2013-03	13172567	3031	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	232
CASCADA Convertible	D1AO	2013-01	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	105
CASCADA Convertible	D1AO	2014-06	2021-12	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	1,274
Combo	263	2012-03	2018-04	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	15,877
Combo Combi	263	2012-02	2018-09	53104671	3007	Schrader Snap-in GEN4 type 433MHz Fiat	5
Corsa	GM 4530	2015-03	2019-11	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	210,954
CORSA Mk III	GM S4400	2014-06	2014-10	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	9,923
Corsa Van	GM S4400	2014-06	2014-10	13581562	3027	Schrader Snap-in GEN4 type 433MHz GM	291
Corsa Van	GM 4530	2015-03	2019-12	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	6,907
Insignia	E2JO	2017-06	2023-09	13597645	3025	Schrader Snap-in Faraday 433MHz GM	28,646
INSIGNIA Mk I	GM G3700	2014-05	2017-06	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	47,020
MERIVA	GM S4470	2014-08	2017-05	13581561	3062	Schrader Snap-in GEN4 type 433MHz GM	15,214
MOKKA	G1UO	2012-09	2015-08	22853740	3049	Schrader Snap-in GEN4 type 433MHz GM	25,883
MOKKA	G1UO	2015-09	2019-12	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	117,593
MOVANO Mk II	X62	2014-06	2020-11	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	17,521
VIVA	M2JO	2015-05	2022-08	13598773	3063	Schrader Snap-in Faraday 433MHz GM (China)	32,776
Vivaro	X82	2015-01	2019-10	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	69,432
Vivaro Combi	X82	2015-02	2020-01	407009322R-D	3041	Schrader Snap-in HS with 20deg angle 433MHz Renault	4,184
ZAFIRA Mk II	GM A3370	2011-07	2014-12	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	5,128
ZAFIRA Mk III	GM P3470	2011-12	2014-05	13348393	3026	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,814
ZAFIRA Mk III	GM P3470	2014-06	2022-02	13581560	3033	Schrader Clamp-in Gen Gamma 433MHz GM	44,139

Euroguide -Sensors Look Up

Sensors Look Up: This list identifies which cars can be fitted with a particular Schrader referenced part number.

- 1/ Identify the Schrader Code of the sensor (After Market reference) in the first column "**Schrader Part Number**"
- 2/ In the same column identify which car manufacturer and car model the sensor is fitted on.
– When the sensor reference is matching the right car model, all the necessary information concerning the car and the sensor are in the following columns (same line, from left to the right).
- 3/ **Car Model Code** is the Identification code of the vehicle.
- 4/ "**Start of Application**" and "**End of Application**" show if the car has been fitted with a TPMS direct system by the car manufacturer during this period of time.
- 5/ **OE Sensor reference:** This is car manufacturer's part number for the sensor.
- 6/ **Sensor Description:** Description of the After Market reference.
- 7/ **Direct TPMS car park in Market:** number of vehicles introduced in the reference market with direct TPMS systems using the specific sensor indicated in the OE sensor reference column.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated.
For further information: tpmseuroshop.com or aftermarket@schrader.co.uk

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Schrader Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
3000							
Citroen							
Berlingo	B9	2008-01	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	5,576
C4 Picasso I	B58	2006-05	2015-12	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	4,678
Jumper	X2/50	2006-02	2013-11	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	2,948
DS							
DS4	B75	2010-12	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	2,985
DS5	B81	2011-06	2014-01	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	2,111
Peugeot							
3008	T84	2008-11	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	7,148
308	T7	2007-07	2013-12	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	276
308 SW	T7	2007-05	2013-08	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	7,709
5008	T87	2009-09	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	3,649
RCZ	T75	2009-12	2013-09	Schrader	5430W0	Schrader Snap-in GEN4 type 433MHZ PSA	666
3001							
Citroen							
Jumpy Combi	G9	2006-09	2014-06	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	857
Fiat							
Scudo	G9	2007-01	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	981
Scudo Combi	G9	2006-09	2013-10	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	199
Peugeot							
EXPERT	G9	2006-10	2013-12	Schrader	9677130580	Schrader Snap-in GEN4 type 433MHZ PSA HP	1,752
3002							
Citroen							
Berlingo	B9	2013-10	2016-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	61,893
Berlingo							145,039
C5	X7	2013-09	2017-11	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	25,347
C-Elysee	M3/M4	2012-10	2022-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	95,070
DS							
DS4	B75	2014-02	2020-08	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	48,778
DS5	B81	2014-02	2018-11	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	25,660
Peugeot							
207 SW	A7	2013-09	2016-03	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	4,953
207 Van	A7	2005-11	2014-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	322
3008	T84	2013-09	2017-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	90,539
301	M3/M4	2012-10	2022-03	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	61,490
308 SW	T73	2013-09	2016-03	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	4,100
408	T73	2012-07	2019-03	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	7,387
5008	T87	2013-09	2017-04	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	51,120
508 SW	W2	2013-09	2017-06	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	80,270
PARTNER	B9	2014-06	2019-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	293,734
PARTNER Tepee	B9	2014-06	2019-09	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	83,193
RCZ	T75	2013-10	2016-12	Schrader	9811536380	Schrader Snap-in HS with 20deg angle 433MHZ PSA	4,209
3003							
Citroen							
Jumpy	G9	2014-06	2016-12	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	26,513

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Jumpy Combi	G9	2014-07	2016-12	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	3,423
Fiat							
Scudo	G9	2013-11	2017-04	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	19,555
Scudo Combi	G9	2013-11	2017-04	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	1,899
Peugeot							
EXPERT	G9	2014-06	2016-09	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	21,750
EXPERT Tepee	G9	2014-06	2017-06	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	4,754
Toyota							
PROACE	G9	2014-06	2016-08	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	7,150
PROACE	K0	2016-06	2025-06	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	34,842
PROACE Combi	G9	2014-06	2016-09	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	68
PROACE Combi	K0	2016-08	2025-03	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	1,231
Proace Verso	K0	2016-06	2025-06	Schrader	9808859080	Schrader Snap-in HS with 20deg angle 433MHZ PSA HP	9,778
3005							
Dodge							
AVENGER	JS41D	2007-03	2014-10	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	3
CALIBER	PM49	2006-04	2012-12	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	5
Jeep							
CHEROKEE	KK	2008-01	2014-04	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	71
CHEROKEE	KJ	2001-07	2015-03	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	3
Compass	MK49	2006-09	2017-09	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	3,183
PATRIOT	MK74	2014-01	2017-11	Schrader	56029481AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	25
PATRIOT		2007-04	2013-12	Schrader	56029359AC	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	7
3007							
Alfa Romeo							
MITO	955	2013-08	2019-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHz Fiat	44,790
Chrysler							
GRAND VOYAGER V	RT	2011-01	2015-11	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	145
GRAND VOYAGER V							1,182
YPSILON (Direct)	846	2011-08	2017-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	271
Citroen							
Nemo	225	2007-11	2015-12	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	12,841
Nemo Multispace	225	2007-10	2018-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	2,716
Dodge							
CHALLENGER Coupe	LC22	2010-02	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	18
DURANGO	WD75	2011-04	2020-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	379
JOURNEY	JC49	2011-01	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	41
JOURNEY		2014-07	2020-06	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHZ Chrysler	115
Ram	DS	2009-01	2013-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	98
Fiat							
DOBLO	263	2010-02	2020-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	266,944
DOBLO COMBI	263	2010-01	2019-07	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	3,576
Fiorino	225	2007-10	2022-03	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	16,162
Fiorino Qubo	225	2007-10	2022-03	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	4,005
FREEMONT	JF	2014-07	2016-06	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHZ Chrysler	11,664
FREEMONT		2011-03	2014-06	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	3,885
GRANDE PUNTO	199	2007-09	2014-05	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	915
GRANDE PUNTO		2006-01	2014-05	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	18,683
LINEA	200	2007-03	2015-03	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	15,415
Qubo	225	2008-01	2015-09	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	662
STRADA	178	1999-01	2019-04	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	599
Jeep							
GRAND CHEROKEE IV	WK74	2010-05	2016-03	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	17,924
Wrangler	JK	2010-10	2013-12	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	710
Wrangler		2014-01	2018-12	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHZ Chrysler	15,141
Wrangler	JL	2018-04	2026-08	Schrader	68241067AA	Schrader Snap-in GEN4 type 433MHZ Chrysler	5,628
Lancia							
DELTA III	844	2014-06	2016-12	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	699
VOYAGER	RT	2011-09	2013-07	Schrader	56029398AB	Schrader Snap-in GEN4 type 433MHZ Chrysler	305
Opel							
Combo	263	2012-01	2018-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	44,672
Combo Combi	263	2011-11	2018-06	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	6,555
Vauxhall							
Combo	263	2012-03	2018-04	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	15,877
Combo Combi	263	2012-02	2018-09	Schrader	53104671	Schrader Snap-in GEN4 type 433MHZ Fiat	5
3008							
Chrysler							
300C	LX	2012-06	2016-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	27
300C		2012-04	2021-04	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHZ Chrysler	13
Lancia							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
THEMA							
3009	LX	2011-02	2016-06	Schrader	56029400AD	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler	285
Alfa Romeo							
4C SPIDER	4C	2013-09	2019-06	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	3,406
Citroen							
Jumper	X2/50	2013-12	2021-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	164,633
Jumper Combi	X2/50	2014-06	2020-09	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	16,581
Fiat							
Ducato	X2/50	2014-06	2021-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	35,924
DUCATO	X2/44,X2/50	2014-06	2020-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	19
Ducato Combi	X2/50	2014-06	2020-09	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	13,468
Maserati							
Ghibli	M157	2013-09	2020-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	13,076
GRAN TURISMO	M145	2014-01	2019-09	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	1,093
GRANCABRIO	M147	2015-07	2019-07	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	565
Levante	M161	2016-03	2023-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	14,219
QUATTROPORTE VI	M156	2013-03	2021-06	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	2,439
Peugeot							
Boxer	X2/50	2013-12	2020-12	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	201,624
Boxer Combi	X2/50	2014-06	2021-03	Schrader	05154876AA	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat	8,021
3011							
Mercedes-Benz							
B-CLASS	W246	2013-01	2019-04	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	255,620
B-CLASS		2011-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	4,935
C-Class	W204	2013-01	2014-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	13,566
C-Class		2007-01	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	6,102
C-CLASS Coupe	C204	2011-04	2016-02	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	8,694
CLA-Class	C117	2013-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10,107
CLC-CLASS	C203	2008-01	2012-05	Schrader	A0035400217	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler	2
CLS-Class	C218	2010-12	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	3,483
E-Class	W212	2009-02	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	25,437
E-CLASS Coupe	C207	2012-12	2018-07	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	26,935
E-CLASS Coupe		2009-01	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	994
GLA-CLASS	X156	2013-12	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	9,510
GL-CLASS	X164	2009-06	2013-06	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	293
GL-CLASS	X166	2012-10	2017-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	17,492
GLK	X204	2012-12	2016-03	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,632
GLK		2008-08	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,661
M-CLASS	W166	2011-10	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	1,666
R-CLASS	V251	2013-01	2015-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	71
R-CLASS		2009-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	122
S-CLASS	W221	2009-07	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	382
SL	R231	2012-01	2014-05	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	553
SLK	R172	2013-01	2014-11	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,755
SLK		2011-03	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	732
SLS AMG Roadster	C197	2013-01	2015-02	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	124
SLS AMG Roadster		2010-02	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	45
Sprinter	NCV3	2014-06	2018-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	357,395
Sprinter	T1N	2013-10	2020-02	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	18,115
Sprinter Combi	NCV3	2012-10	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	61
Sprinter Combi		2013-01	2018-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	27,961
VITO Tourer	VS20	2014-10	2023-12	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	57,234
Smart							
forfour	W454	2004-01	2015-02	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	10
FORTWO	A451	2013-01	2016-04	Schrader	A0009057200	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	15,843
FORTWO		2007-01	2012-12	Schrader	A0009054100	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Daimler	2,850
3012							
Mercedes-Benz							
VARIO	T2N	2014-01	2015-03	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	6
V-CLASS	VS20	2014-03	2024-01	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	122,832
Vito	VS20	2014-08	2023-10	Schrader	A4479050500	Schrader Snap-in HS with 10deg angle 433MHz Daimler	205,342
3013							
Aston Martin							
DB11	VH500	2016-07	2025-06	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	2,611
Infiniti							
Q30	GD1A	2016-04	2022-11	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,532
Q30		2015-12	2022-09	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	20,542
Mercedes-Benz							
A-CLASS	S176	2012-07	2018-10	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	443,828
AMG GT	C190	2014-10	2022-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	8,621
C-Class	W205	2014-01	2021-09	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	559,309
C-CLASS Coupe	C205	2015-11	2023-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	105,346

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
CLA-Class	C117	2014-12	2019-08	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	228,359
CLS-Class	C218	2014-12	2018-05	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	21,416
E-Class	W212	2014-12	2018-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	80,127
G-Class	W464	2018-05	2032-06	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	4,780
G-CLASS Cabrio	G463/461	2014-03	2020-04	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	19,766
GLA-CLASS	X156	2014-12	2020-09	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	244,604
GLC	X253	2015-06	2022-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	246,794
GLC Coupe	C253	2016-07	2023-09	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	69,233
GLE	W166	2015-06	2019-02	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	83,790
GLE Coupe	C292	2015-04	2020-03	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	49,773
GLS	X166	2015-12	2019-08	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	13,394
M-CLASS	W166	2014-07	2016-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	14,542
S-CLASS	W222	2013-07	2020-12	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	56,491
S-CLASS Coupe	C217	2014-04	2022-10	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	11,615
SL	R231	2014-06	2020-09	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	5,979
SLK	R172	2014-12	2018-05	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	9,017
SLK		2014-03	2021-06	Schrader	A0009050030	Schrader Clamp-in Gen Gamma 433MHz Daimler	18,964
3018							
Ford							
Escape	U377	2007-07	2012-10	Schrader	9L3Z-1A189-A	Schrader Snap-in GEN4 type 315MHz Ford	1
3019							
Ford							
ECOSPORT	B515	2013-08	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,402
TOURNEO CONNECT / GRAND TOURNEO CONNECT Kombi	V408	2013-09	2014-06	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,038
Tourneo Courier	B460	2014-04	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,465
Transit	V347,V348	2014-03	2014-10	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	4,379
Transit Combi	V347	2014-03	2014-05	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	6
Transit Combi	V347,V348	2014-03	2014-06	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	362
Transit Connect	V227	2014-03	2015-08	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	865
Transit Connect	V408	2013-09	2014-03	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	2,019
Transit Courier	B460	2014-04	2014-09	Schrader	DR3V-1A180-BB	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	1,692
3020							
Ford							
EDGE	U387	2007-02	2015-12	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	238
Explorer	U502	2011-05	2015-12	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	2,339
F-150	P415	2009-09	2014-02	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	8
F-Series	P415	2009-09	2014-02	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	9
TOURNEO CUSTOM	V362	2012-07	2018-12	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	80,264
Transit	V363	2014-01	2018-12	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	406,035
Transit		2014-07	2018-12	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	1,588
Transit Combi	V348	2013-06	2014-09	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	245
Transit Connect	V363	2014-04	2018-12	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	28,400
TRANSIT CUSTOM	V362	2012-07	2018-12	Schrader	DV6T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford (China)	407,779
Mazda							
BT-50	J26E	2012-01	2020-09	Schrader	BB5T-1A180-AA	Schrader Snap-in GEN4 type 433MHz Ford	24
3021							
Ford							
B-MAX	B232	2014-03	2018-04	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	116,936
ECOSPORT	B515	2014-10	2017-12	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	144,279
F-150	P415	2014-03	2015-06	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	35
F-150	P552	2015-08	2021-04	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	583
FIESTA VI	B299	2014-03	2017-03	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	553,995
FIESTA VI Van	B299	2014-03	2017-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	17,203
FOCUS III Turnier	C346	2014-03	2020-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	824,151
F-Series	P415	2014-03	2015-06	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	28
GRAND C-MAX Van	C344	2014-03	2022-12	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	275,401
Ka+	B562	2016-06	2021-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	111,481
KUGA II Van	C520	2014-03	2020-06	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	520,081
MONDEO V	CD391	2014-10	2017-08	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	154,557
RANGER	P375	2014-03	2024-06	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	147,182
TOURNEO CONNECT / GRAND TOURNEO CONNECT Kombi	V408	2014-07	2018-02	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	45,058
Tourneo Courier	B460	2014-10	2022-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	147,232
Transit	V348	2014-03	2015-07	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	1,598
Transit Connect	V408	2014-03	2018-02	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	143,240
Transit Courier	B460	2014-10	2022-09	Schrader	EV6T-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	90,649
3023							
Ford							
ECOSPORT	B515	2018-01	2022-06	Schrader	F2GT-1A180-CC	Schrader Snap-in Faraday 433MHz Ford	84,634
EDGE	CD539	2015-10	2022-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	38,093
Explorer	U502	2016-01	2019-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	6,898
Fiesta	B479	2017-05	2023-06	Schrader	F2GT-1A180-CB	Schrader Snap-in Faraday 433MHz Ford	410,319

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Schrader	OE Sensor Reference	Schrader	Sensor Description	Direct TPMS car park in market 2018
Fiesta Van	B479	2017-08	2023-06	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	4,277
FIESTA VI	B299,B479	2017-04	2023-06	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	169
Focus	C519	2018-09	2018-09	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	79,961
GALAXY	CD390	2015-05	2026-06	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	55,079
MONDEO V	CD391	2017-09	2025-04	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	74,671
MUSTANG Coupe	S550	2014-11	2021-10	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	39,210
S-MAX	CD389	2015-06	2020-12	Schrader	F2GT-1A180-CB	Schrader	Schrader Snap-in Faraday 433MHz Ford	100,032
TOURNEO CONNECT / GRAND TOURNEO CONNECT Kombi	V408	2018-03	2022-12	Schrader	F2GT-1A180-CD	Schrader	Schrader Snap-in Faraday 433MHz Ford	13,673
Transit Connect	V408	2018-03	2022-12	Schrader	F2GT-1A180-CD	Schrader	Schrader Snap-in Faraday 433MHz Ford	48,573
3024								
Ford								
MUSTANG Coupe	S197	2004-12	2015-08	Schrader	DR3V-1A180-BA	Schrader	Schrader Clamp-in Fixed 20deg angle 433MHz Ford	192
3025								
Opel								
Insignia	E2JO	2017-04	2023-12	Schrader	13597645	Schrader	Schrader Snap-in Faraday 433MHz GM	111,743
Vauxhall								
Insignia	E2JO	2017-06	2023-09	Schrader	13597645	Schrader	Schrader Snap-in Faraday 433MHz GM	28,646
3026								
Chevrolet								
VOLT	D1JCI	2011-07	2015-11	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	87
Opel								
AMPERA	D1JOI	2011-09	2015-12	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	535
ASTRA H	GM A3300	2011-07	2016-04	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	4,600
ASTRA J	GM P3400	2011-09	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	31,640
CASCADA	D1AO	2013-01	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	675
Insignia	GM G3700	2011-09	2014-04	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,300
ZAFIRA B	GM A3370	2011-07	2015-10	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	6,546
ZAFIRA TOURER C	GM P3470	2011-11	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	7,416
Saab								
9-5	SB650	2010-06	2012-12	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	13
Vauxhall								
AMPERA	D1JOI	2012-01	2015-12	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	206
ASTRA Mk VI	GM P3400	2011-09	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	10,876
CASCADA Convertible	D1AO	2013-01	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	105
ZAFIRA Mk II	GM A3370	2011-07	2014-12	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	5,128
ZAFIRA Mk III	GM P3470	2011-12	2014-05	Schrader	13348393	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,814
3027								
Opel								
ADAM	GM 4403	2013-01	2014-07	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	6,635
CORSA D	GM S4400	2014-06	2014-10	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	446
CORSA D Van	GM S4400	2014-06	2014-10	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	22,142
Vauxhall								
ADAM	GM 4403	2013-01	2014-07	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	2,081
CORSA Mk III	GM S4400	2014-06	2014-10	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	9,923
Corsa Van	GM S4400	2014-06	2014-10	Schrader	13581562	Schrader	Schrader Snap-in GEN4 type 433MHz GM	291
3031								
Fiat								
IDEA	350	2003-09	2012-10	Schrader	51750439	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	98
Lancia								
MUSA	848	2004-07	2013-12	Schrader	51750439	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Fiat/GM	692
Opel								
ASTRA H	GM A3300	2004-07	2014-01	Schrader	13172567	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	42
Vauxhall								
Astra Van	GM A3300	2006-10	2013-03	Schrader	13172567	Schrader	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	232
3033								
Chevrolet								
CORVETTE Convertible	Y1BC	2014-02	2021-05	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	2,308
Opel								
ASTRA J	GM P3400	2014-06	2018-06	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	192,672
ASTRA K Van	GM P3400	2014-06	2016-06	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	240
CASCADA	D1AO	2014-06	2022-06	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	12,144
Insignia	GM G3700	2014-05	2017-11	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	112,144
Zafira	GM P3470	2015-02	2021-12	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	1,057
ZAFIRA TOURER C	GM P3470	2014-06	2022-06	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	128,547
Vauxhall								
ASTRA Mk VI	GM P3400	2014-06	2016-04	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	34,996
CASCADA Convertible	D1AO	2014-06	2021-12	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	1,274
INSIGNIA Mk I	GM G3700	2014-05	2017-06	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	47,020
ZAFIRA Mk III	GM P3470	2014-06	2022-02	Schrader	13581560	Schrader	Schrader Clamp-in Gen Gamma 433MHz GM	44,139
3039								
Infiniti								

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
QX50	P53B	2014-04	2015-12	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	885
QX70	P53C	2013-07	2015-12	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2,905
Nissan							
370 Z Coupe	C53D	2010-11	2014-07	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	122
CUBE	X12B	2009-10	2014-09	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	4
Frontier	D22	2005-10	2015-03	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	2
GT-R	D52E	2010-11	2013-11	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	60
MURANO II	P42D	2008-04	2014-09	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,385
Navara	H60A	2015-12	2016-12	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	23,665
NP300	H61B	2009-01	2015-10	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	9
NP300 NAVARA	H61B	2005-07	2016-11	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	12,807
PATHFINDER III	P61B	2005-01	2015-12	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,854
PIXO	YC5	2009-05	2015-06	Schrader	40700JY00B	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	532
Renault							
KOLEOS	H45	2008-02	2013-12	Schrader	407001AY0A	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan	1,244
3040							
Renault							
Clio	X85	2005-05	2014-10	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	8,290
CLIO Grandtour	X85	2007-03	2013-10	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	1,044
MODUS / GRAND MODUS	J77	2008-02	2012-07	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	9
MODUS / GRAND MODUS		2004-05	2014-12	Schrader	8200253215	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Renault	1,469
3041							
Dacia							
DOKKER	K67	2014-06	2020-06	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	117,415
Dokker Van	K67	2014-06	2020-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	111,315
DUSTER	H79	2010-02	2015-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	104,658
LODGY	J92	2012-03	2022-03	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	114,705
LOGAN	X90	2014-06	2015-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	1
Logan Van	X90	2014-06	2015-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	51
Fiat							
Talento	X82	2016-06	2026-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	37,176
Mercedes-Benz							
Citan	VS10	2012-09	2019-08	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	71,243
CITAN Combi	VS10	2012-09	2019-08	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	19,027
Nissan							
NV300	X82	2016-10	2026-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	14,299
NV300 Combi	X82	2016-09	2026-06	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,480
NV400	X62	2014-06	2020-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	24,153
NV400 Combi	X62	2014-06	2020-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	984
TERRANO	H79N	2014-06	2019-10	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	46,613
Opel							
Movano	X62	2014-06	2020-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	57,189
Movano Combi	X62	2014-06	2020-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	2,731
Vivaro	X82	2014-10	2020-02	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	101,988
Vivaro Combi	X82	2014-10	2020-02	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	44,905
Renault							
Captur	J87	2013-02	2015-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	160,212
CLIO IV	X98	2012-08	2019-06	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	137,599
DOKKER	F67.K67	2014-06	2018-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	522
KANGOO / GRAND KANGOO	X61	2007-12	2019-07	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	176,439
Kangoo Passenger	X61	2007-10	2019-08	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	39,495
LODGY	J92	2012-12	2022-03	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	639
LOGAN II	X52	2014-07	2015-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	28,195
MASTER III	X62	2014-03	2020-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	308,940
MASTER Passenger	X62	2014-03	2021-02	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	8,459
SANDERO/STEPWAY II	B52	2014-07	2015-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	19,849
Trafic	X82	2014-04	2026-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	270,727
Trafic	X83	2014-03	2015-01	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	3,566
TRAFIC Passenger	X82	2014-04	2026-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	59,103
TRAFIC Passenger	X83	2014-03	2016-02	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	740
TWINGO II	X44	2014-03	2016-12	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	6,360
TWINGO III	X07	2014-06	2025-04	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	295,853
TWINGO VAN	X07	2014-08	2025-01	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	1,166
WIND	X33	2010-06	2014-06	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	90
Smart							
FORFOUR	W453	2014-09	2025-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	123,034
FORTWO Coupe	C453	2014-09	2025-09	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	219,151
Vauxhall							
MOVANO Mk II	X62	2014-06	2020-11	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	17,521
Vivaro	X82	2015-01	2019-10	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	69,432
Vivaro Combi	X82	2015-02	2020-01	Schrader	407009322R--D	Schrader Snap-in HS with 20deg angle 433MHz Renault	4,184
3042							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Renault							
ESPACE IV	J81	2002-08	2015-10	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	609
ESPACE IV			2016-02	Schrader	8200023746	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHz Renault	2,241
3046							
Volvo							
XC90 I	Y289	2002-04	2015-05	Schrader	30748354	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz Volvo	3,031
3049							
Cadillac							
CTS	GMX226	2011-04	2016-06	Schrader	20922901	Schrader Snap-in GEN4 type 433MHz GM	28
ESCALADE	GMT926	2006-09	2015-05	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	144
ESCALADE	K2UL	2014-06	2020-11	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	3,537
SRX	GMT166	2010-02	2016-10	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	710
Chevrolet							
AVEO	G1SC	2010-12	2022-07	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	14,857
AVEO	T250	2006-01	2014-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	107
Captiva	C100	2006-08	2018-11	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	7,403
COBALT	G1LC	2013-01	2019-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,766
CRUZE	D1SC	2008-10	2018-09	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	23,902
EPICA (Snap-in)	V250	2006-04	2013-07	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	79
Express	GMT610	2003-01	2022-03	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	42
LACETTI (Snap-in)	J200	2003-06	2014-12	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	930
Malibu	V300	2012-01	2014-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	269
ORLANDO	D1NC	2010-09	2018-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	4,939
Silverado	K2XC	2013-08	2019-03	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	162
Spark	M1JC	2009-07	2019-09	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	7,571
Spark	M200	2005-02	2015-07	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	22
TAHOE (Snap-in)	GMT921	2006-06	2017-12	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	166
TAHOE (Snap-in)	K2UC	2014-07	2020-06	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	906
Trailblazer (Snap-in)	GM31UX	2013-05	2015-04	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	385
TRAX	G1UC	2012-07	2017-03	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	3,074
TRAX		2013-06	2020-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	1,596
Daewoo							
Gentra	J200	2004-04	2016-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	19,930
Matiz	M100	2014-01	2018-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	7,134
NEXIA	T	2014-01	2016-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	6,347
GMC							
YUKON	GMT922	2006-09	2014-06	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	14
YUKON	K2UG	2014-07	2020-08	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	441
Hummer							
HUMMER H3	GMT345	2005-08	2012-11	Schrader	25789964	Schrader Snap-in GEN4 type 433MHz GM	1
Opel							
ANTARA	C105	2010-11	2015-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	7,276
MOKKA	G1UO	2012-07	2015-08	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	80,558
Vauxhall							
ANTARA	C105	2010-11	2015-12	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	2,645
MOKKA	G1UO	2012-09	2015-08	Schrader	22853740	Schrader Snap-in GEN4 type 433MHz GM	25,883
3054							
Cadillac							
ATS	A1SL	2013-04	2018-12	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	311
CTS	A1LL	2014-03	2019-06	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	619
Chevrolet							
Camaro	A1BC	2016-01	2022-05	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	3,678
CAMARO Convertible	GMX521	2009-08	2016-10	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	670
CORVETTE Convertible	GMX245	2010-02	2014-05	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	27
EPICA (Clamp-in)	V250	2006-04	2013-07	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	79
LACETTI (Clamp-in)	J200	2003-06	2014-12	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	930
TAHOE (Clamp-in)	GMT921	2006-06	2017-12	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	166
TAHOE (Clamp-in)	K2UC	2014-07	2020-06	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	906
Trailblazer (Clamp-in)	GM31UX	2013-05	2015-04	Schrader	20925925	Schrader Clamp-in Gen J 433MHz GM	385
3055							
Cadillac							
CTS	GMX322	2007-11	2014-11	Schrader	25774007	Schrader Clamp-in Gen J 433MHz GM	41
3056							
Hyundai							
VELOSTER	FS	2011-03	2018-02	Schrader	52933-2V100	Schrader Snap-in GEN4 type 433MHz HKMC	1,304
3057							
Alpina							
Alpina 5	G30	2017-05	2025-03	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	267
XD3	G01	2018-02	2025-01	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	140
BMW							
3-Series	G20	2018-10	2026-12	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	6,410
5-Series	G30	2017-01	2018-02	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	126,139

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
5-Series	G30	2018-03	2024-10	Schrader	6887140-01	Schrader Clamp-in Gen Delta 433MHz BMW	109,678
6 Gran Coupe	F12	2018-11	2019-12	Schrader	6887140-01	Schrader Clamp-in Gen Delta 433MHz BMW	287
6-Series GT	G32	2017-08	2025-01	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	10,449
7-Series	G11	2015-09	2018-02	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	29,697
7-Series		2018-03	2022-10	Schrader	6887140-01	Schrader Clamp-in Gen Delta 433MHz BMW	8,498
8-Series	G14	2018-09	2026-03	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	595
X3	G01	2017-11	2018-02	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	11,959
X3		2018-03	2025-03	Schrader	6887140-01	Schrader Clamp-in Gen Delta 433MHz BMW	46,697
X4	G02	2018-06	2025-12	Schrader	6887140-01	Schrader Clamp-in Gen Delta 433MHz BMW	11,467
Mercedes-Benz							
A-CLASS	W177	2018-06	2026-07	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	89,214
CLS	C257	2018-01	2025-04	Schrader	A0009052102	Schrader Clamp-in Gen Delta 433MHz Daimler	12,069
E-Class	C238	2017-03	2025-04	Schrader	A0009052102	Schrader Clamp-in Gen Delta 433MHz Daimler	41,160
E-Class	W213	2016-02	2024-02	Schrader	A0009052102	Schrader Clamp-in Gen Delta 433MHz Daimler	282,400
GLE	V167	2018-12	2026-02	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	1,140
Sprinter	VS30	2018-10	2031-12	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	1,714
Sprinter		2018-04	2031-12	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	61,393
Rolls-Royce							
CULLINAN	RR31	2018-05	2026-04	Huf	A0009054104	Beru-Huf Clamp-in 433MHz BMW / Mercedes	167
PHANTOM	RR11	2017-09	2028-06	Schrader	36106872774	Schrader Clamp-in Gen Delta 433MHz BMW	146
3058							
Lotus							
ELISE	Monza	2000-09	2020-06	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,354
EVORA	Eagle	2009-06	2022-06	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	753
Exige	Monza	2000-10	2020-12	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	1,050
Saab							
9-3X	SB440	2007-07	2014-04	Schrader	B121G600F	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHz GM	104
3059							
Hyundai							
Creta	GS	2016-08	2022-03	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	139,362
i10	IA	2013-10	2020-05	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	325,657
Kia							
SOUL II	PS	2013-11	2019-09	Schrader	52933-B2100	Schrader Snap-in HS with 20deg angle 433MHz HKMC	77,137
3060							
Hyundai							
Creta (Russia Only)	GS	2016-08	2022-03	Schrader	52933-C8000	Schrader Snap-in Faraday 433MHz HKMC	15,485
i20	GB	2014-10	2021-03	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	411,536
iX35 (Direct)	LM	2015-10	2017-02	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	17,097
NEXO	FE	2018-06	2024-10	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	103
Santa Fe	TM	2018-04	2025-03	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	8,992
Sonata	LF	2014-09	2020-03	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	4,643
Tucson	TL	2015-06	2021-09	Schrader	52933-C1100	Schrader Snap-in Faraday 433MHz HKMC	511,886
3061							
Kia							
QUORIS	KH	2013-02	2019-06	Schrader	52933-3T000	Schrader Snap-in Faraday 433MHz HKMC	951
3062							
Chevrolet							
Malibu	V300	2014-07	2016-12	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	211
NIVA II	2123	2014-06	2023-03	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	113,443
Mahindra							
Bolevo	CL/MM	2014-06	2016-08	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	1
GOA	W105	2015-02	2021-01	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	430
SCORPIO	W105	2015-02	2021-01	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	489
XUV500	W201	2014-06	2021-03	Schrader	1805BA0131N-A	Schrader Snap-in GEN4 type 433MHz Mahindra	1,339
Opel							
ADAM	GM 4403	2014-08	2020-12	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	140,787
Corsa	GM 4530	2014-12	2019-12	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	631,042
CORSA E	GM 4530	2014-11	2019-12	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	11,298
MERIVA B	GM S4470	2010-04	2017-09	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	95,149
Vauxhall							
ADAM	GM 4403	2014-08	2020-05	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	29,373
Corsa	GM 4530	2015-03	2019-11	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	210,954
Corsa Van	GM 4530	2015-03	2019-12	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	6,907
MERIVA	GM S4470	2014-08	2017-05	Schrader	13581561	Schrader Snap-in GEN4 type 433MHz GM	15,214
3063							
Cadillac							
CT6	O1SL	2016-08	2018-12	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	232
XT5	C1UL	2016-08	2017-12	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM (China)	861
Chevrolet							
Malibu	E2SC	2017-02	2018-12	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	119
Opel							
Ampera-e	G2KCZ	2017-01	2023-09	Schrader	13589601	Schrader Snap-in Faraday 433MHz GM	3,521

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
ANTARA	C105	2016-01	2017-06	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	1,433
Karl	M2JO	2015-02	2022-07	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	124,766
MOKKA	G1UO	2015-09	2020-03	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	383,624
Vauxhall							
ANTARA	C105	2016-01	2017-04	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	704
MOKKA	G1UO	2015-09	2019-12	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	117,593
VIVA	M2JO	2015-05	2022-08	Schrader	13598773	Schrader Snap-in Faraday 433MHz GM (China)	32,776
3064							
Subaru							
FORESTER	FM5	2014-01	2019-06	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	66,801
FORESTER	PF3	2014-01	2014-12	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
Impreza	MF1	2014-01	2017-03	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,654
IMPREZA	ZR1	2014-01	2015-12	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	90
LEGACY	EZ5	2014-01	2015-12	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	495
LEVORG	VL9	2015-06	2021-03	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	10,559
OUTBACK	BF4	2014-09	2020-09	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	749
OUTBACK		2014-08	2017-12	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	23,802
OUTBACK	EZ5	2014-03	2015-08	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	1,111
TREZIA	217A	2014-01	2017-01	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	115
TRIBECA	00X	2014-01	2015-06	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	6
WRX	VL9	2014-03	2018-12	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	2,970
XV	MF1	2014-01	2017-09	Schrader	28103FJ000	Schrader Snap-in HS with 20deg angle 433MHz Subaru	25,999
3066							
Ram							
1500	DT	2018-06	2024-12	Schrader	68293199AA	Schrader Snap-in Gen6 PAL Potted 433MHz Chrysler	389
3068							
Ssangyong							
ACTYON I	C100	2014-03	2017-02	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	124
Actyon Sports	Q150	2014-03	2018-06	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	401
ACTYON SPORTS II	Q150	2014-11	2018-06	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	1,482
Actyon SUT	Q150	2014-03	2018-06	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	697
Actyon SUT	Q200	2018-07	2024-12	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	59
KORANDO	C200/AS11	2014-06	2018-12	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	4,876
KORANDO		2013-07	2020-07	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	467
KORANDO		2013-08	2019-09	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	12
KORANDO C	C200/AS11	2013-08	2019-12	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	14,403
Korando Sports	Q200	2018-07	2025-02	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	478
KYRON	D100	2014-06	2016-09	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	2,400
REXTON	Y200	2014-05	2018-12	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	6,434
RODIUS	A100	2014-05	2018-12	Schrader	41990-34000	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL	7,450
3069							
Volvo							
S60	V431	2018-12	2024-10	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	298
S60 Cross Country	V431	2018-12	2024-10	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	16
S90	V541	2016-05	2024-03	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	26,235
V60	V432	2018-08	2024-10	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	12,949
V60 Cross Country	V432	2018-10	2024-09	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	3,275
V90 Cross Country	V542	2016-12	2022-09	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	23,546
XC90 II	V526	2015-01	2016-03	Schrader	31362304	Schrader Snap-in HS with 20deg angle 433MHz Volvo	21,654
3071							
Opel							
ASTRA K	D2JO	2015-09	2022-09	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	477,479
ASTRA K	D2JO	2016-01	2021-12	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	720
Vauxhall							
ASTRA Mk VII	D2JO	2015-10	2022-04	Schrader	13594222	Schrader Snap-in Faraday 433MHz GM	135,940
3073							
Renault							
CLIO IV	X98	2014-06	2015-12	Schrader	407009987R	Schrader Snap-in Faraday 433MHz Renault T4	242,907
3076							
Subaru							
FORESTER	ES1	2018-10	2023-12	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	450
Impreza	HR3	2017-01	2022-03	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	3,152
OUTBACK	BF4	2018-01	2020-09	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	8,470
TRIBECA	TR8	2018-11	2024-09	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	128
XV	HQ4	2017-08	2022-09	Schrader	28103FL000/FL00A	Schrader Snap-in Faraday 433MHz Subaru	21,978
3108							
Volkswagen							
AMAROK	VN417	2018-03	2024-03	Schrader	2N0907251	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	5,413
Crafter	VN54T	2018-03	2027-07	Schrader	2N0907251	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	39,359
Crafter Combi	VN54T	2018-03	2027-04	Schrader	2N0907251	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	1,010
Transporter	VN46T	2018-03	2024-10	Schrader	2N0907251	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	96,753
Transporter Shuttle	VN46T	2018-03	2024-06	Schrader	2N0907251	Schrader GEN6 WAL GEN DELTA 433 MHz Tx Volkswagen	1,854

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
3131							
Genesis							
G70	IK	2017-12	2026-06	Schrader	52933-J5000	Schrader Snap-in Faraday 433MHz HKMC	91
Kia							
Stinger	CK	2017-08	2023-09	Schrader	52933-J5000	Schrader Snap-in Faraday 433MHz HKMC	6,545
3139							
Cadillac							
XT4	E2UL	2018-11	2024-12	Schrader	13516165	Schrader Snap-in Faraday 433MHz GM Basic TFA	14
XT5	C1UL	2018-01	2022-02	Schrader	13516165	Schrader Snap-in Faraday 433MHz GM Basic TFA	630
Chevrolet							
Traverse	C1YC	2017-12	2023-11	Schrader	13516165	Schrader Snap-in Faraday 433MHz GM Basic TFA	634
4001							
Alfa Romeo							
8C SPIDER	920	2007-10	2015-03	Huf	99760602100	Beru-Huf Clamp-in Separate valve G1 433MHz Porsche	5
Ferrari							
599 GIB/GTO	F141	2006-04	2013-02	Huf	185189	Beru-Huf Clamp-in Separate valve G1 433MHz Fiat Group	4
4009							
Aston Martin							
DB9 Volante	AM803	2004-04	2018-01	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	568
DBS Vantage	AM803	2007-11	2014-03	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	11
Rapide	VH400	2010-01	2020-11	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	554
VANQUISH Volante	AM310	2012-11	2020-04	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,053
Vantage	VH600	2017-12	2025-06	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,581
VANTAGE Roadster	AM305	2005-07	2018-01	Huf	AD43-360671-AA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,971
VIRAGE Volante	AM803	2011-05	2012-12	Huf	CD23-360671-CA	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	11
Audi							
A6 Allroad	AU561	2006-03	2012-09	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	78
A6 Allroad	AU571	2012-02	2018-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,515
A6 Avant	AU571	2011-01	2019-01	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	114,197
A8	AU641	2010-01	2018-03	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	16,014
Q7	AU716	2005-11	2014-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,423
R8 Spyder	AU714	2007-02	2015-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	773
Bentley							
CONTINENTAL Cabriolet	BY614	2006-07	2012-05	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	3
CONTINENTAL Cabriolet	BY624	2012-02	2018-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,064
CONTINENTAL Coupe	BY624	2011-01	2018-03	Huf	4F0907275B	Beru-Huf Clamp-in Separate valve G2.2 433MHz VW/Porsche	2,818
CONTINENTAL FLYING SPUR	BY611	2005-03	2013-04	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	11
CONTINENTAL FLYING SPUR	BY631	2018-09	2026-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	198
Continental GT	BY634	2017-12	2025-09	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,059
FLYING SPUR	BY621	2013-04	2018-10	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,168
MULSANNE	BY731	2010-09	2022-01	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	814
Ferrari							
458 Spider	F142	2009-09	2016-10	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,096
488 Spider	F142M	2015-09	2019-07	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	3,970
CALIFORNIA	F149	2008-12	2017-12	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	1,727
CALIFORNIA	F149(2)	2018-01	2025-07	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	889
F12 Berlinetta	F152	2012-09	2020-12	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,322
FF	F151	2011-05	2020-03	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	1,306
Lamborghini							
AVENTADOR Coupe	LB734	2011-06	2020-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,215
GALLARDO	LB614	2003-07	2016-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	54
HURACÁN	LB624	2014-06	2022-06	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	2,133
Maserati							
GRAN TURISMO	M145	2010-09	2013-12	Huf	282189	Beru-Huf Clamp-in Separate valve G2.4 433MHz Fiat	52
GRANCABRIO	M147	2009-11	2015-06	Huf	99760602120	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	147
QUATTROPORTE V	M139	2010-01	2013-06	Huf	228887	Beru-Huf Clamp-in Separate valve G2.3 433MHz Fiat	6
McLaren							
MP4 Coupe	P11	2011-03	2018-06	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	513
Sports Series	P13	2015-12	2023-03	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	1,300
Super Series	P14	2017-07	2025-03	Huf	11B0015CP	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	910
Porsche							
911	997	2008-04	2013-01	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	26
911	PO674	2011-09	2016-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	21,645
918 Spyder	PO715	2014-05	2015-09	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	109
BOXSTER	987	2008-11	2012-12	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	32
BOXSTER Spyder	981	2012-04	2016-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	7,408
CAYENNE	PO526	2010-04	2014-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	4,169
CAYMAN	981	2013-04	2016-08	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	5,037
CAYMAN	987	2009-02	2013-03	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	43
PANAMERA	PO613	2009-06	2013-09	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	552
Rolls-Royce							
PHANTOM Drophead Coupe	RR02	2007-08	2017-01	Huf	36236798726	Beru-Huf Clamp-in Separate valve G2.4 433MHz BMW	102

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
SEAT							
EXEO ST	SE411	2013-06	2015-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	24
Tesla							
ROADSTER	DarkStar	2008-03	2012-07	Huf	2000680	Beru-Huf Clamp-in Separate valve G1.2 433MHz Fiat Group	5
Volkswagen							
PHAETON	VW611	2007-06	2016-09	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,590
TOUAREG	VW526	2010-04	2014-07	Huf	7PP907275F	Beru-Huf Clamp-in Separate valve G2.4 433MHz VW/Porsche	1,791
4010							
Alpina							
Alpina 5	F10	2010-10	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	17
D3 Kombi	E90	2009-01	2012-12	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	7
XD3	F25	2013-07	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8
BMW							
1-Series	E80	2004-06	2014-11	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	1,899
3-Series E90	E90	2009-10	2016-12	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,944
5-Series	F10	2010-01	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	14,120
5-Series GT	F07	2009-09	2014-02	Huf	36106790054	Beru-Huf Clamp-in Separate valve G3.3 433MHz BMW	697
6 Gran Coupe	F12	2012-03	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	487
6-Series	F12	2011-01	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	636
7-Series	F01	2010-09	2016-01	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	4,258
X1	E84	2009-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8,579
X3	F25	2010-11	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	8,265
X5	E70	2010-03	2014-04	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,130
X6	E71	2011-12	2015-01	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,816
Z4 Roadster	E89	2010-09	2014-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	786
Mini							
MINI CLUBMAN	R55	2009-08	2016-01	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	2,277
MINI CLUBVAN	R55	2013-01	2015-05	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	99
MINI COUNTRYMAN	R60	2010-08	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	10,564
MINI Coupe	R58	2011-07	2016-05	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,898
MINI PACEMAN	R61	2012-11	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,355
MINI Roadster	R59	2011-12	2014-06	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	738
Rolls-Royce							
Dawn	RR06	2016-02	2022-03	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	685
GHOST	RR04	2010-09	2020-02	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	887
PHANTOM	RR01	2012-01	2017-07	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	96
WRAITH	RR05	2013-08	2021-03	Huf	36106856227	Beru-Huf Clamp-in Separate valve G3.41 433MHz BMW	1,031
4011							
Volkswagen							
CC	VW464	2012-01	2017-07	Huf	3AA907275B	Beru-Huf Clamp-in Separate valve G3.42 433MHz VW	1,207
PASSAT	VW471	2010-10	2014-07	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	11,609
Passat CC	VW464	2008-03	2017-07	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	5,214
TIGUAN	VW316	2007-08	2016-12	Huf	3AA907275D	Beru-Huf Clamp-in Separate valve G3.3 433MHz VW	57,713
4012							
Audi							
A3 Sportback	AU370	2012-11	2020-01	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	91,025
A4 Avant	AU491	2015-08	2023-10	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	21,656
A5	AU484	2007-01	2015-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,147
A5	AU494	2016-10	2023-12	Huf	5Q0907275B	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29,042
A5 Cabrio	AU494	2017-04	2024-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,779
A5 Cabriolet	AU484	2008-11	2017-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	13,308
A5 Sportback	AU484	2009-07	2017-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,076
A5 Sportback	AU494	2018-01	2024-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,649
A6	AU581	2018-07	2026-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,284
A6 Allroad	AU581	2018-12	2026-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	525
A7	AU583	2018-04	2025-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,923
A7 Sportback	AU573	2010-09	2018-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,970
A8	AU651	2017-10	2024-11	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,411
Q2	AU276	2016-07	2024-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	176,557
Q3	AU316	2011-07	2019-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	58,358
Q3	AU326	2018-11	2025-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,708
Q5	AU416	2008-09	2017-08	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25,826
Q5	AU426	2016-09	2023-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	29,520
Q7	AU716	2014-06	2015-10	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	5,376
Q8	AU536/3	2018-08	2025-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,168
R8	AU624	2015-10	2024-05	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,851
TT Roadster	AU434	2014-07	2022-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	12,577
Bentley							
BENTAYGA	BY636	2016-02	2023-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	4,461
Lamborghini							
Urus	LB636	2018-06	2025-11	Huf	5Q0907275B	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	516
Porsche							
911	PO674	2016-09	2020-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	36,199
BOXSTER Spyder	981	2016-09	2020-09	Huf	9A790727502	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,059
CAYENNE	PO536	2017-10	2025-04	Huf	9A790727502	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	22,911
CAYENNE	PO526	2014-09	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	43,063

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
CAYMAN	981	2016-09	2020-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,999
MACAN	PO416	2014-02	2021-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	96,053
PANAMERA	PO623	2016-10	2024-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	25,375
PANAMERA	PO613	2013-10	2017-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	6,162
Skoda							
CITIGO	SK120	2011-12	2020-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	139,095
FABIA III Kombi	SK260	2014-10	2021-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	61,232
FABIA VAN	SK260	2014-11	2021-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	276
Kodiaq	SK326/1	2016-10	2023-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	14,192
OCTAVIA	SK371	2013-02	2020-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	97,470
OCTAVIA	SK351	2014-06	2016-08	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1
RAPID	SK351/3	2012-09	2019-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,948
Rapid Spaceback	SK350/3	2013-08	2019-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,522
SUPERB	SK461	2008-04	2016-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,465
SUPERB	SK481	2015-05	2022-08	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	27,616
YETI	SK316	2009-06	2018-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	17,667
Volkswagen							
AMAROK	VN417	2009-11	2018-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	63,281
Arteon	VW483	2017-05	2024-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,790
BETLE	VW325	2012-12	2020-07	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	15,282
Caravelle	VN750	2003-04	2016-08	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	11,039
Crafter	VN830	2014-02	2017-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	20,380
Crafter Combi	VN830	2014-02	2017-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	683
EOS	VW465	2006-02	2016-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	667
GOLF PLUS	VW369	2008-12	2014-01	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,872
GOLF SPORTSVAN	VW379	2014-03	2021-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	60,857
GOLF SPORTSVAN		2014-07	2021-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	2,212
GOLF VI	VW360	2008-09	2021-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,581
GOLF VI	VW362	2009-09	2014-10	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,501
GOLF VII	VW370	2012-09	2020-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,867,791
Jetta	VW371	2018-06	2025-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	1,584
JETTA IV	VW361	2010-11	2018-11	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	34,732
Multivan	VN750	2004-03	2015-10	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	173
NEW BEETLE	VW324	2011-09	2020-03	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	10,541
PASSAT	VW471	2014-08	2015-09	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	7,085
PASSAT	VW481	2014-10	2021-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	229,272
Polo	VW270	2017-09	2024-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	123,395
SCIROCCO	VW364	2008-06	2018-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	8,957
SHARAN	VW428	2010-07	2023-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	34,431
TIGUAN	VW326	2016-01	2024-11	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	203,578
TOUAREG	VW526	2014-08	2018-07	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,887
TOUAREG	VW536	2018-09	2025-02	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	3,567
TOURAN	VW368	2015-01	2016-12	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	9,433
TOURAN	VW378	2015-09	2022-06	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	95,384
Transporter	VN750	2003-04	2016-01	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	19,796
Transporter Shuttle	VN750	2004-03	2016-04	Huf	5Q0907275	Beru-Huf Clamp-in Separate valve G3.4 433MHz VW/Porsche	528
4015							
Lancia							
FLAVIA Cabriolet	JS27	2012-05	2014-11	Conti	68078768AA	Conti Clamp-in TG1C 433MHz Chrysler	67
4016							
Chrysler							
Pacifica	RU	2017-10	2023-12	Conti	53394085	Conti Snap-in TG1D 433MHz Chrysler	112
Jeep							
Compass	MP	2017-05	2022-12	Conti	53305555	Conti Snap-in TG1D 433MHz Chrysler	63,874
Compass	551	2017-10	2023-08	Conti	53305555	Conti Snap-in TG1D 433MHz Chrysler	5,781
RENEGADE	520	2014-08	2021-12	Conti	68105280AF	Conti Snap-in TG1D 433MHz Chrysler	242,339
4018							
Jeep							
GRAND CHEROKEE IV	WK74	2016-04	2020-02	Conti	68252495AA	Conti Clamp-in TG1C 433MHz Jeep FCA	30,520
4019							
Jaguar							
F-TYPE Coupe	X152	2013-02	2020-12	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	16,035
XJ	X351	2010-01	2020-01	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	6,684
XK Coupe	X150	2014-03	2015-11	Conti	C2D21599	Conti Clamp-in TG1C 433MHz Ford	374
Land Rover							
DEFENDER (Alloy wheels)	L316	1987-03	2019-07	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	19,588
Discovery	L319	2004-07	2017-05	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	28,991
DISCOVERY SPORT	L550	2014-10	2022-09	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	146,857
FREELANDER 2	L359	2006-10	2016-11	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	7,255

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
RANGE ROVER EVOQUE Cabriolet	L538	2011-07	2018-07	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	177,897
RANGE ROVER IV	L405	2012-09	2015-05	Conti	LR021935	Conti Clamp-in TG1C 433MHz Ford	9,472
RANGE ROVER SPORT	L494	2013-07	2015-05	Conti	FW931A159AB	Conti Clamp-in TG1C 433MHz Conti Volvo	14,807
RANGE ROVER SPORT	L320	2010-05	2013-10	Conti	FW931A159AB	Conti Clamp-in TG1C 433MHz Conti Volvo	1,139
4021							
Ford							
S-MAX	CD340	2006-02	2017-03	Conti	8G921A159-AE	Conti Clamp-in TG1C 433MHz Ford	14,287
4023							
Ford							
GALAXY	CD340	2006-01	2015-12	Conti	8G921A189-KB	Conti Clamp-in TG1B 433MHz Ford	9,674
Mondeo	CD345	2007-01	2016-01	Conti	8G921A189-KB	Conti Clamp-in TG1B 433MHz Ford	16,156
Jaguar							
XF SPORTBRAKE	X250	2007-12	2017-09	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	13,982
XK Coupe	X150	2006-02	2014-02	Conti	LR032835	Conti Clamp-in TG1B 433MHz Ford	197
Land Rover							
RANGE ROVER III	L322	2001-10	2012-12	Conti	RQH500470	Conti Clamp-in TG1B 433MHz Ford	330
Volvo							
C30	Y279	2006-09	2014-03	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	563
C70 II Cabriolet	Y281	2006-03	2015-12	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	258
S40 II	Y276	2003-12	2014-05	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	327
V50	Y280	2003-11	2014-01	Conti	30681555	Conti Clamp-in TG1B 433MHz Ford	1,086
4026							
Hyundai							
i10	PA	2007-10	2017-06	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	5,625
i30	FD	2007-05	2015-04	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	1,344
Kia							
CEE'D	ED	2006-12	2014-05	Conti	52933-2L600	Conti Clamp-in TG1B 433MHz HKMC	2,369
4027							
Hyundai							
i20	PB	2008-10	2015-07	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	29,641
Solaris	RB	2011-01	2017-03	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	188,129
SONATA VI	YF	2010-03	2015-12	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	46
Kia							
Optima	TF	2010-10	2016-07	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	6,193
SORENTO II	XM	2009-03	2012-09	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	776
SOUL	AM	2008-09	2013-10	Conti	52933-1J000	Conti Clamp-in TG1C 433MHz HKMC	753
4028							
Fiat							
124	J12F	2016-04	2023-06	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	17,362
Mazda							
2	J03	2015-02	2021-08	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	29,732
2	J64F	2007-07	2016-06	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	9,871
2	J03W	2015-01	2021-08	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	80,379
3	J68C	2008-11	2017-01	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	3,452
5	J74G	2010-10	2018-01	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	558
6	J61A	2007-12	2012-08	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	821
6		2012-09	2013-12	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	625
6	J71E	2012-11	2020-12	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	12,246
CX-3	J03K	2015-02	2019-12	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	174,565
CX-5	J53C	2012-01	2017-09	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	158,745
CX-5	J72A	2017-03	2020-04	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	12,440
CX-7	J31H	2006-07	2014-10	Conti	GS1D37140	Conti Clamp-in TG1C 433MHz Mazda	46
CX-9	J50C	2007-03	2016-06	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	84
MX-5 III	J04C	2005-12	2015-08	Conti	BB337140B	Conti Clamp-in TG1C 433MHz Mazda	255
MX-5 IV	J12A	2016-06	2022-06	Conti	BHB637140	Conti Clamp-in TG1C 433MHz Mazda	4,211
4031							
Citroen							
C5	X7	2007-10	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,638
C6	X6	2005-09	2013-03	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	65
C8	V3	2005-09	2014-07	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	516
Lancia							
VOYAGER	RT	2013-08	2018-09	Conti	9673198580/9681102280	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	2,137
Peugeot							
207 SW	A7	2005-11	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	6,481
508 SW	W2	2010-09	2013-09	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	5,641
807	V2	2004-10	2015-06	Conti	5430T4	Conti Clamp-in TG1B Siemens VDO 433MHz PSA	743
4032							
Lada							
VESTA	2180	2015-10	2026-07	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	220,932
Nissan							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Almera	LB1A	2013-05	2020-04	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	70,638
Atleon	F24	2014-10	2019-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	14
Cabstar	F24	2014-10	2020-03	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	23,281
Cabstar E	F24	2014-10	2020-03	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	167
NOTE	J02C	2013-09	2017-12	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	84,157
NOTE	L11E	2004-09	2014-10	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	3,355
NP300	D22	1999-01	2018-02	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	952
NP300 NAVARA Pick-up	H60A	2016-05	2024-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,891
NT500	F91G	2014-02	2017-03	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,673
NV200 / EVALIA Bus	X11M	2012-01	2019-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	188
NV200 Combi	X11M	2009-11	2020-03	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	21,299
Pulsar	B12L	2014-07	2018-12	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	96,885
QASHQAI II	P32S	2014-01	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	366,880
Sentra	L12F	2013-11	2017-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	7,365
TEANA III	L42L	2014-03	2018-11	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	4,198
Tiida	B12D	2012-08	2013-10	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	262
Tiida	B12L	2015-03	2015-11	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	1,574
X-TRAIL	P32R	2013-12	2016-09	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	92,292
Renault							
KOLEOS	H45	2014-01	2017-06	Conti	407003VU0A	Conti Clamp-in TG1C 433MHz Renault	5,693
4034							
Lada							
GRANTA	2190	2014-03	2022-03	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	424,014
KALINA	1117-1119	2014-03	2017-05	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	529
KALINA	2192	2013-07	2020-03	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	93,808
Nissan							
LEAF	B12P	2018-01	2021-12	Conti	40700 - 4CB1B	Conti Snap-in TG1D 433MHz Renault	22,174
Micra	B02E	2017-02	2023-06	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	184,653
NV200	X11M	2009-09	2019-09	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	59,352
QASHQAI II	P32S	2016-10	2021-07	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	623,055
X-TRAIL	P32R	2016-10	2021-03	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	194,905
Renault							
ESPACE V	JFC	2015-04	2021-03	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	64,875
KADJAR	HFE	2015-04	2021-06	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	369,886
KOLEOS	HZG	2016-10	2022-06	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	35,185
Megane	LFF	2016-09	2024-09	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	101,165
Megane	XFB	2015-11	2023-09	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	436,407
MEGANE VAN	XFB	2016-02	2023-06	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	14,561
Scenic	JFA	2016-09	2023-06	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	213,623
TALISMAN	XFD	2015-09	2022-09	Conti	407004CB0A	Conti Snap-in TG1D 433MHz Renault	92,317
4035							
Renault							
FLUENCE	L38	2009-11	2017-10	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	61,570
Laguna Coupe	D91	2008-08	2015-11	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	893
LAGUNA III Grandtour	X91	2007-06	2016-12	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	9,341
LATITUDE	L43	2010-09	2016-08	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	931
Megane	B32	2016-04	2009-11	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	4,531
Megane	B32_X95	2009-03	2017-01	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	3,830
MEGANE	X95	2008-10	2017-01	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	136,780
MEGANE VAN	X95	2008-10	2016-10	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	5,155
Scenic	J95	2009-04	2017-05	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	147,473
Zoe	X10	2012-09	2022-12	Conti	407000435R	Conti Clamp-in TG1C Siemens VDO 433MHz Renault	96,385
4038							
Mercedes-Benz							
Sprinter (Lo Line)	NCV3	2006-06	2014-05	Conti	2E0907508F / 2E0907508J	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	18,885
VIANO (Lo Line)	W639	2003-07	2016-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,869
VIANO (Mid-Line)	W639	2003-07	2016-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,869
Vito (Lo Line)	W639	2003-05	2015-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	5,249
Vito (Mid-Line)	W639	2003-05	2015-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	5,249
Vito Combi (Lo Line)	W639	2003-05	2015-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,227
Vito Combi (Mid-Line)	W639	2003-05	2015-04	Conti	A0025409517	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	1,227
Volkswagen							
Crafter (Lo Line)	VN830	2006-04	2014-01	Conti	2E0907508F / 2E0907508J	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	1,254
Crafter Combi	VN830	2006-04	2014-01	Conti	2E0907508F / 2E0907508J	Conti Clamp-in MB_no RF link Siemens VDO 433MHz VW	39
4040							
Mercedes-Benz							
SL	R230	2005-01	2012-06	Conti	A0025406717	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler	3
4043							
Alpina							
B4 Coupe	F32	2013-12	2021-07	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	506
D3 Kombi	F30	2013-01	2020-06	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	858
BMW							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
1-Series	F20	2017-01	2019-04	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	277,511
1-Series		2011-08	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	233,825
2-Series	F22	2013-11	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	45,700
2-Series		2017-01	2022-09	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	60,931
2-Series Active Tourer	F45	2017-01	2022-05	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	113,414
2-Series Active Tourer		2014-07	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	93,570
2-Series Gran Tourer	F46	2017-01	2022-09	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	58,999
2-Series Gran Tourer		2015-04	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	44,382
3-Series F30	F30	2011-11	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	238,857
3-Series F30		2017-01	2019-12	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	229,607
3-Series GT	F34	2017-01	2020-08	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	30,042
3-Series GT		2013-03	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	34,323
4-Series	F32	2017-01	2021-01	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	54,847
4-Series		2013-07	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	57,291
4-Series Gran Coupe	F32	2017-01	2021-07	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	71,377
4-Series Gran Coupe		2014-04	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	57,642
i3	I01	2017-01	2020-10	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	45,286
i3		2013-09	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	21,220
i8	I12	2017-01	2023-05	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	2,549
i8		2014-05	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	2,825
X1	F48	2015-09	2022-10	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	325,329
X2	F39	2018-01	2025-03	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	37,702
X5	F15	2017-01	2019-02	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	81,787
X5		2013-09	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	73,293
X6	F16	2014-09	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	25,299
X6		2017-01	2020-01	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	30,048
Mini							
Countryman	F60	2016-12	2024-01	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	103,332
MINI Cabriolet	F56	2013-12	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	201,850
MINI Cabriolet		2017-01	2023-03	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	279,708
MINI Cabriolet	R56	2006-08	2016-02	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	16,219
MINI CLUBMAN	F54	2017-01	2022-12	Conti	36106881890	Conti Clamp-in TG1C 433MHz BMW	59,475
MINI CLUBMAN		2015-09	2016-12	Conti	36106856209	Conti Clamp-in TG1C 433MHz BMW	30,338
4044							
Lexus							
ES	041L	2006-11	2013-02	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
GS	620N	2005-03	2012-08	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12
IS C	030L	2005-10	2013-04	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	135
LS	250L	2006-10	2012-12	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
Toyota							
RAV 4 III	120L	2005-11	2014-03	Pacific	42607-50010	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,269
4045							
Aston Martin							
CYGNET	630L	2011-04	2014-10	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	17
Lexus							
CT	080A	2011-02	2021-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	32,006
ES (High Line)	980L	2012-09	2018-12	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,399
ES (High Line)	240B	2018-10	2024-12	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	84
ES (Lo Line)	980L	2012-09	2018-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,595
ES (Lo Line)	240B	2018-10	2024-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	337
GS (High Line)	920L	2012-03	2019-09	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,354
GS (Lo Line)	920L	2012-03	2019-09	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,415
GX	837L	2010-03	2023-03	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	3,796
IS III	400A	2013-05	2020-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	22,981
LC (High Line)	950A	2017-07	2025-06	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	192
LC (Lo Line)	950A	2017-07	2025-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	766
LS (High Line)	250L	2013-01	2018-05	Pacific	42607-30070	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	140
LS (Lo Line)	250L	2013-01	2018-05	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	561
LX	220L	2013-01	2015-08	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,206
NX	600A	2014-09	2019-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	86,083
RC	720A	2014-11	2021-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,495
RX	640L	2009-04	2016-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8,922
Subaru							
BRZ	E88	2012-05	2021-07	Pacific	SU003 05268	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	1,827
Toyota							
Alphard	480L	2012-02	2015-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	112
Alphard	580A	2015-07	2021-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	2,391
AURIS TOURING SPORTS	130A	2012-12	2019-04	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	454,391
AVENSIS	445L	2008-12	2018-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	103,548
Aygo	200A/201A	2014-07	2022-08	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	299,247
CAMRY	050A	2012-01	2017-08	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	80,131
Corolla	150B	2018-12	2023-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	4,274
Corolla	133L/252L	2007-10	2014-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	120

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Corolla	150L	2007-01	2016-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,332
COROLLA	079L_140N_340N	2002-01	2018-06	Pacific	42607-42020	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
COROLLA	150A	2014-08	2019-03	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	10,794
COROLLA	466A	2013-07	2018-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	171,611
COROLLA	252L	2007-07	2014-07	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	6,316
Dyna	131N	2012-01	2021-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,071
FJ CRUISER	155L	2006-05	2018-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	8
Fortuner	669L	2014-07	2017-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	568
GT 86 Coupe	E88	2012-04	2021-06	Pacific	SU003 05268	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota/Subaru	6,266
HIACE	550N	2005-01	2019-03	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,216
HIACE Combi	550N	2004-08	2017-09	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	16
HIGHLANDER	440A	2014-04	2020-09	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,774
Hilux	669L	2009-01	2017-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	38,800
HILUX VIII Pick-up	640A	2015-07	2023-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	97,931
IQ	630L	2008-11	2016-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,433
Land Cruiser	611L	2009-09	2017-07	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12,827
LAND CRUISER 200	215L	2007-11	2017-08	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	834
LAND CRUISER 200		2012-01	2015-08	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	12,314
Land Cruiser Prado	611L	2009-11	2017-07	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,097
MIRAI	470A	2017-12	2019-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	119
Previa	085L	2007-01	2020-09	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1
Prius	590L	2009-06	2016-10	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	9,577
Prius	690A	2015-11	2021-06	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	39,787
Prius Plus	030A	2012-04	2018-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	23,599
RAV 4 IV	410A	2013-02	2019-04	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	372,770
Sequoia	200L	2008-02	2021-12	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	29
Sienna	580L	2010-06	2021-04	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	296
TUNDRA	480A/180L	2007-04	2022-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	153
URBAN CRUISER	260L	2008-12	2016-07	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	292
VENZA	470L	2009-04	2017-05	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	1,623
VERSO	595L	2009-02	2018-07	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	88,877
VERSO S	770L	2011-01	2017-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	5,730
YARIS	850L	2011-08	2021-01	Pacific	42607-02031	Pacific Clamp-in Fixed Angle ver 1 433MHz Toyota	748,452
4047							
Infiniti							
Q70	L53E	2013-10	2018-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,137
QX50	P53B	2016-01	2018-06	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,517
QX50	P71A	2018-02	2024-04	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,000
QX70	P53C	2016-01	2019-06	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	5,991
QX80	Z62	2014-04	2022-07	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,470
Nissan							
370 Z Roadster	RC53D	2014-08	2018-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	524
GT-R	D52E	2013-12	2019-06	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	2,545
JUKE	P12C	2010-08	2015-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	88,526
LEAF	B12G	2010-11	2015-09	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	10,757
Murano	P42M	2015-01	2021-07	Pacific	40700-6WY0A	Pacific Clamp-in Fixed Angle ver 1 433MHz Nissan	6,665
4051							
Hyundai							
iX35 (High Line)	LM	2013-11	2015-09	TRW	52933-2Y450	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	37,741
Kia							
SPORTAGE (High Line)	SL	2014-04	2015-12	TRW	52933-2Y450	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	31,290
4052							
Hyundai							
iX35 (Direct)	LM	2010-01	2013-10	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	10,097
Kia							
SPORTAGE	SL	2010-06	2014-03	TRW	52933-3M000	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	18,706
4053							
Hyundai							
Elantra	MD	2010-11	2017-06	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	13,527
ELANTRA	HD	2006-10	2014-03	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	22
Kia							
Cerato	TD	2009-02	2016-04	TRW	52933-3X305	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	922
CERATO	YD	2013-02	2019-06	TRW	52933-3X305	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	28,598
Rio (Lo Line)	QB	2011-12	2017-12	TRW	52933-3X305	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	188,434
Rio (Lo Line)	UB	2011-06	2017-06	TRW	52933-3X300	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	110,205
4054							
Alfa Romeo							
159 Sportwagon	939	2005-07	2013-11	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	185
MITO	955	2008-06	2013-07	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,515
SPIDER	946	2006-07	2014-05	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	4
Chrysler							
DELTA	844	2011-08	2013-07	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	28

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Fiat							
Bravo	198	2007-01	2016-10	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	2,234
Lancia							
DELTA III	844	2008-05	2014-05	TRW	51839114	TRW Clamp-in Variable Angle ver 2 433MHz Fiat	1,339
4055							
Ford							
RANGER	J97U	2006-12	2013-01	Lear	6F2Z-1A189A	(blank)	27
4057							
Hyundai							
SANTA FE II	CM	2005-12	2014-10	Lear	52933-2B000	Lear Snap-in Fixed Angle ver 1 433MHz HKMC	354
4058							
Tesla							
MODEL S	Model S	2013-01	2014-08	Baolong	FS15I1	Baolong Clamp-in Variable angle detachable valve 433MHz Tesla	1,510
4060							
Genesis							
G80	DH	2017-09	2020-04	Conti	52933-B1100	Conti Clamp-in TG1C 433MHz HKMC	384
Hyundai							
Accent	HC	2017-04	2023-10	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	10,517
ACCENT IV	RB	2011-03	2018-09	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	54,377
EQUUS	VI	2009-07	2016-04	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	641
GENESIS	DH	2014-02	2020-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	3,243
GENESIS Coupe	BK	2008-09	2017-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	128
i30	GD	2012-01	2018-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	179,075
i20	JC	2010-09	2018-06	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	105,280
i55	EN	2007-01	2016-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	139
PORTER	HR	2006-01	2017-12	Conti	52933-A5100	Conti Clamp-in TG1C 433MHz HKMC	713
SANTA FE III	DM	2012-06	2019-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	74,779
Solaris	HC	2017-04	2023-03	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	111,423
Kia							
Cadenza	VG	2011-01	2017-03	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	63
CARENS III	UN	2006-08	2012-12	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	31
CARENS IV	RP	2013-01	2019-12	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	69,602
CEE'D	JD	2012-04	2018-04	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	275,915
Mohave	HM	2008-12	2019-02	Conti	52933-2J100	Conti Clamp-in TG1C 433MHz HKMC	2,008
Picanto	TA	2011-02	2018-02	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	116,018
SORENTO II	XM	2012-10	2015-07	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	8,375
SORENTO III	UM	2014-11	2021-12	Conti	52933-2M650	Conti Clamp-in TG1C 433MHz HKMC	78,193
VENGA	YN	2009-11	2018-06	Conti	52933-3N100	Conti Clamp-in TG1C 433MHz HKMC	83,609
4061							
Hyundai							
i40	VF	2011-04	2014-03	TRW	52933-3V100	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	4,838
4062							
Hyundai							
i35	LM	2011-01	2016-07	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	1,349
iX35 (Lo Line)	LM	2013-11	2015-09	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	37,741
Kia							
SPORTAGE (Lo Line)	SL	2014-04	2015-12	TRW	52933-2S400	TRW Clamp-in Fixed Angle ver 1 433MHz HKMC	73,009
4065							
Fiat							
SEDICI	YY2	2014-06	2015-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	584
Opel							
AGILA	H0310	2014-06	2015-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2,104
Suzuki							
ALVIO	YL1	2018-09	2021-04	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	136
ALTO	YC5	2014-06	2016-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	6,497
Baleno	YR	2015-12	2022-04	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	48,032
CELERIO	YLA	2014-09	2020-09	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	81,236
GRAND VITARA II	YT4	2014-06	2020-09	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	9,701
Ignis	YJ	2016-07	2022-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	86,231
Jimny	YR7	2014-06	2018-10	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	44,586
Jimny	YR7(2)	2018-08	2025-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	6,708
Jimny	YR6	2014-06	2018-08	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	3,216
Jimny Wide	YR7(2)	2018-11	2025-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	148
KIZASHI	YW1	2014-06	2016-06	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	66
SPLASH	YV1	2014-06	2016-11	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	3,266
Swift	YP6,YP7	2014-06	2017-05	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	65,711
Swift	YS	2017-02	2023-06	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	76,926
SWIFT IV	YP6	2014-06	2017-06	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	18,067
SX4	YY1	2014-06	2015-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	694
SX4	YY1,YY3	2014-06	2015-12	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2,264
SX4 S-Cross	YAA	2014-09	2020-03	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	2,713
SX4 S-Cross		2013-09	2020-06	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	117,626

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
VITARA	YFA	2015-02	2021-04	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	260,578
Vauxhall							
AGILA	H0310	2014-06	2015-09	Conti	43139-61M00	Conti Clamp-in TG1C 433MHz Suzuki	614
4066							
Jaguar							
E-PACE	X540	2017-11	2025-03	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	24,642
F-PACE	X761	2016-01	2023-09	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	78,399
I-PACE	X590	2018-03	2025-09	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	3,911
XE	X760	2015-04	2022-03	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	67,746
XF	X260	2015-09	2024-03	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	43,361
Land Rover							
Discovery	L462	2017-01	2025-06	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	36,766
Range Rover Evoque	L551	2018-08	2027-03	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	15,535
RANGE ROVER IV	L405	2015-06	2019-12	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	56,345
RANGE ROVER SPORT	L494	2015-06	2020-09	Conti	LR070840	Conti Clamp-in TG1C 433MHz JLR	90,854
Range Rover Velar	L560	2017-05	2024-12	Conti	C2D47173	Conti Clamp-in TG1C 433MHz JLR	38,899
4068							
Dodge							
Ram	DS	2013-07	2021-12	TRW	68239720AB	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	2,246
Jeep							
CHEROKEE	KL	2013-11	2020-09	TRW	68249197AA	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	29,940
Ram							
1500 Standard Cab Pickup	DS	2012-01	2017-12	TRW	68239720AB	TRW Snap-in Fixed Angle ver 1 433MHz Chrysler	1,861
4069							
Alpina							
Alpina 5	F10	2014-03	2017-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	142
XD3	F25	2014-03	2018-01	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	349
BMW							
5-Series	F10	2014-03	2017-08	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	162,034
5-Series GT	F07	2014-03	2017-12	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,276
6 Gran Coupe	F12	2014-03	2018-10	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	9,944
6-Series	F12	2014-03	2017-12	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,079
6-Series		2018-01	2019-06	Huf	36 10 6 890 964	Beru-Huf Clamp-in 433MHz BMW	771
X1	E84	2014-03	2015-12	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	28,942
X3	F25	2014-03	2018-07	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	131,630
X4	F26	2014-03	2017-12	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	63,852
X4		2018-01	2018-12	Huf	36 10 6 890 964	Beru-Huf Clamp-in 433MHz BMW	11,460
Z4 Roadster	E89	2014-03	2019-02	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,207
Mini							
MINI COUNTRYMAN	R60	2014-07	2017-04	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	58,086
MINI PACEMAN	R61	2014-07	2017-03	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	6,092
MINI Roadster	R59	2014-07	2017-02	Huf	36106798872	Beru-Huf Clamp-in 433MHz BMW	1,165
4070							
Volvo							
S70	Y555	2014-07	2020-12	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	53,757
V40	Y555	2014-07	2020-09	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	208,919
V60	Y352	2014-07	2017-09	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	77,654
V60		2015-05	2018-08	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	27,248
V70 III	Y285	2014-07	2016-12	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	33,522
XC60	Y413	2014-07	2016-09	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	108,932
XC70 II	Y285	2014-07	2017-12	Conti	31445473	Conti Clamp-in TG1C 433MHz Volvo	26,880
4071							
Infiniti							
Q50	L53H	2013-09	2019-09	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	11,286
Q60	D53H	2016-08	2023-06	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	1,288
QX60	P42J	2014-04	2019-06	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	2,511
Nissan							
Murano (Russia Only)	P42M	2015-01	2021-07	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	3
PATHFINDER IV	P42K	2014-03	2019-12	Conti	407003JA0A	Conti Clamp-in TG1C 433MHz Conti Nissan	3,487
4072							
Honda							
Accord	2GA	2013-04	2019-08	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	929
Accord	QP	2013-04	2016-12	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	1,091
Accord CrossTour	2LX	2018-01	2024-02	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	658
ACCORD VIII	QE	2013-04	2016-02	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	1,155
CROSSTOUR	2NX	2012-01	2016-02	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	30
CROSSTOUR		2011-04	2015-11	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	328
Jazz	2HQ	2014-03	2015-09	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	487
JAZZ III	2AP	2014-03	2016-07	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	16,386
JAZZ IV	2WF	2015-03	2020-06	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	108,608
Qoros							
3	CF11	2017-09	2021-12	Conti	42753-TL0-G520	Conti Clamp-in TG1C 433MHz Conti Honda	16

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
4073							
Citroen							
C4 AIRCROSS	J4	2014-06	2017-12	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	21,484
C-ZERO	S4	2014-06	2018-09	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	4,142
Fiat							
Fullback	4P00	2016-04	2023-06	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	19,886
Mitsubishi							
ASX	ZC	2014-06	2021-02	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	155,047
i-Miev	TQ	2014-06	2019-12	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	1,838
L200	4P00	2015-01	2024-09	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	81,126
L200	CR	2014-06	2016-02	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	9,164
LANCER VIII Sportback	GS41	2014-06	2019-01	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	8,510
OUTLANDER III	RE	2014-06	2020-06	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	198,270
Spacestar	EL	2014-06	2020-04	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	97,760
Peugeot							
4008	J3	2014-06	2018-01	Conti	1612477080	Conti Clamp-in TG1C 433MHz Conti PSA	4,546
ION	S3	2014-06	2018-11	Conti	4250C477	Conti Clamp-in TG1C 433MHz Conti Mitsubishi	5,161
4077							
Nissan							
MICRA IV	B02A	2010-07	2019-06	Pacific	40700-3HN0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	126,377
PATROL VI	Y62	2014-06	2023-03	Pacific	40700-3HN0B	Pacific Clamp-in Fixed Angle 433MHz Nissan	1,052
4078							
Hyundai							
GRANDEUR	HG	2011-06	2014-02	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	67
i40	VF	2014-04	2021-09	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	81,419
Kia							
Rio (High Line)	QB	2011-12	2017-12	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	47,109
Rio (High Line)	UB	2011-06	2017-06	TRW	52933-3V600	TRW Clamp-in Variable Angle ver 1 433MHz HKMC	27,551
4079							
Mitsubishi							
Attrage	EL-L	2014-05	2020-04	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	1,121
Eclipse Sport	NS	2017-12	2024-03	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	41,681
Mirage	EL	2013-02	2020-01	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	5,189
PAJERO IV	BK	2014-07	2025-09	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	28,391
PAJERO SPORT II	CR45	2014-06	2016-06	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	4,926
PAJERO SPORT III	4P45	2016-05	2024-06	Conti	4250C275	Conti Snap-in TG1D 433MHz Conti Mitsubishi	12,359
4081							
Tesla							
Model 3	Model E	2018-01	2028-06	Conti	1034602-00-A	Conti Clamp-in TG1C 433MHz Tesla	2,606
MODEL S	Model S	2014-09	2020-02	Conti	1034602-00-A	Conti Clamp-in TG1C 433MHz Tesla	53,202
MODEL X	Model X	2016-05	2023-08	Conti	1034602-00-A	Conti Clamp-in TG1C 433MHz Tesla	30,078
4083							
Great Wall							
Steed	K5/K6	2018-01	2020-03	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	123
STEED	K2/K4	2014-06	2017-12	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	1,114
Voleex C30	CH041	2014-03	2018-11	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	383
Wingle	K2/K4	2014-06	2016-05	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	328
Wingle	K5/K6	2017-07	2023-10	SATE	3641110AK80XA	SATE Clamp-in 433MHz Great Wall	1,126
4084							
Ssangyong							
REXTON	Y400	2017-09	2024-08	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	4,756
TIVOLI	X100	2015-03	2022-03	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	26,745
Tivoli XLV	X105	2016-04	2022-06	Huf	41990-35000	Huf Snap-in 433MHz Huf Ssangyong	6,757
4085							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Genesis							
G90	HI	2017-04	2023-04	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	515
Hyundai							
Elantra	AD	2015-06	2021-08	Conti	52933-F2000	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	37,742
GRANDEUR	HG	2014-03	2017-07	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	115
GRANDEUR	IG	2017-05	2023-09	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	607
Ioniq	AE	2016-06	2021-06	Conti	52933-F2000	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	50,079
KONA	OS	2017-09	2023-09	Conti	52933-F2000	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	69,882
Kia							
Niro	DE	2016-05	2021-09	Conti	52933-F2000	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	76,401
Optima	JF	2015-09	2021-09	Conti	52933-D4100	Conti Clamp-in TG1C 433MHz HKMC Conti LoS Optima	66,646
4086							
Karma							
KARMA	K1	2011-06	2014-01	Lear	C131124501000	Lear Snap-in Fixed Angle ver 1 433MHz Fisker sensor	21
4087							
Kia							
Cadenza	YG	2017-04	2022-06	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	239
Picanto	JA	2017-01	2023-06	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	116,177
SPORTAGE	QL	2016-01	2021-12	Conti	52933-D9100	Conti Clamp-in TG1C 433MHz HKMC Conti QL Platform	449,546
4089							
Hyundai							
H-1	TQ	2014-03	2021-09	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	6,452
H-1 Cargo	TQ	2014-03	2018-09	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	279
H-1 Combi	TQ	2014-03	2014-12	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	5
H-1 Travel	TQ	2014-03	2018-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	3,037
H-1 Van	TQ	2014-03	2018-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	464
H100	TQ	2014-03	2018-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	3,231
H100 Van	HR	2004-03	2017-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	4,952
H100 Van	TQ	2014-03	2018-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1,010
Kia							
K2700	HR	2014-06	2017-06	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	1
K2700	PU	2014-06	2018-12	Conti	52933-4H100	Conti Clamp in TG1C 433MHz HKMC H1 Starex	13,874
4091							
Great Wall							
HOVER H6	CHB021/CHB022	2013-11	2018-04	SATE	3641100XKZ16A	SATE Clamp-in 433MHz Great Wall ASK	2,250
4092							
Great Wall							
Hover H2	CH071/CH072	2017-03	2018-10	SATE	3641100XKW09A	SATE Clamp-in 433MHz Great Wall FSK	362
4094							
Infiniti							
EX	P53B	2011-01	2017-09	Pacific	40700-1LA0E	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	339
FX	P53C	2011-01	2019-09	Pacific	40700-1LA0E	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	678
G-Series	L53A	2011-01	2014-06	Pacific	40700-1LA0E	Pacific Clamp in Gen 2 Nissan Infiniti 315MHz	105
4102							
Alfa Romeo							
Giulia	952	2016-04	2022-12	Conti	50547691	Conti Clamp-in TG1C 433MHz Alfa Giulia	55,206
Stelvio	949	2017-01	2023-12	Conti	50547691	Conti Clamp-in TG1C 433MHz Alfa Giulia	40,603
4113							

Schrader Part Number (NEW)	Car Model Code	Start of Application	End of Application	Sensor Manufacturer	OE Sensor Reference	Sensor Description	Direct TPMS car park in market 2018
Kia							
Cee'd	CD	2018-05	2024-07	Pacific	52940-J7000	Pacific Clamp-in Fixed Angle ver 1 433MHz Hyundai	31,865
4114							
Lexus							
LS	200B	2018-02	2025-03	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	1,362
LX	220L	2015-09	2020-09	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	16,321
RX	740A	2015-12	2022-06	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	46,521
Toyota							
Camry	050A	2017-09	2020-06	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	42,752
C-HR	560A	2016-11	2023-03	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	248,926
Land Cruiser	611L	2017-08	2022-03	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	8,113
LAND CRUISER 200	215L	2015-09	2020-12	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	52,728
LAND CRUISER 200		2017-08	2020-06	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	4
Land Cruiser Prado	611L	2017-08	2023-12	Pacific	42607-48020	Pacific Clamp-in Fixed Angle ver 1 433MHz Lexus	20,446
4115							
Mercedes-Benz							
X-Class	VS40	2017-09	2026-12	Pacific	A4709057800	Pacific Snap-In 433Mhz Nissan	14,463
Nissan							
JUKE	P12C	2015-10	2019-09	Pacific	40700-5ZH0A	Pacific Snap-In 433Mhz Nissan	289,621
LEAF	B12G	2017-01	2018-05	Pacific	40700-5ZH0A	Pacific Snap-In 433Mhz Nissan	18,993
Navara	H60A	2017-01	2023-12	Pacific	40700-5ZH0A	Pacific Snap-In 433Mhz Nissan	58,794
Renault							
Alaskan	U60A	2017-06	2026-06	Pacific	40700-5ZH0A	Pacific Snap-In 433Mhz Nissan	8,199
4121							
Infiniti							
M	L53E	2009-12	2016-04	Pacific	40700-1LL0D	Pacific Clamp in Nissan Infiniti 433MHz	171
QX56	Z62	2010-07	2012-12	Pacific	40700-1LL0D	Pacific Clamp in Nissan Infiniti 433MHz	69
QX80	Z62	2013-11	2014-03	Pacific	40700-1LL0D	Pacific Clamp in Nissan Infiniti 433MHz	49
Nissan							
PATROL VI	Y62	2010-02	2014-05	Pacific	40700-1LL0D	Pacific Clamp in Nissan Infiniti 433MHz	136

Euroguide -Service Kits Look Up

Service Kits Look Up: The application sensor list applied to a service kit is a list detailing which sensors can be serviced with that particular service kit. The number besides the code represents the quantity included in package (for example 5001-10 means a package containing 10 Service kits)

- 1/ The first column "**Service Kits Part Nr./ Schrader Part Number (NEW)**" lists each service kit and identifies the sensors matching with the selected service kit (red references)
- 2/ The second column titled "**Service Kit Description**" shows the description of the selected service kit.
- 3/ The remaining column details the After Market "**Sensor Description**" of the sensor that can be serviced with the selected service kit.

TPMS Euroshop makes every effort to ensure that the information contained in this list are correct, but cannot guarantee 100% accuracy of the information. Customers should be aware that they buy and use any products on this website at their own risk. This list will be regularly updated. For further information: tpmseuroshop.com or aftermarket@schrader.co.uk

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
5001-10		
3042	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault grommet seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Small Grommet Seal 433MHZ Renault
5002-10		
3040	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Renault
3043	Service kit for SEL Clamp-in Gen2 type 433MHZ Renault conical seal coloured rings (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 10deg angle Conical Seal 433MHZ Renault
5003-10		
3004	Service Kit for SEL Clamp-in Gen2 type 433MHZ PSA PWM (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Large Grommet Seal 433MHZ PSA
5004-10		
3026	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3031	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ GM
3037	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Nissan
3046	Service Kit for SEL Gen2 conical seal (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Conical Seal 433MHZ Volvo
3058	Service Kit for SEL Gen2 conical seal (Pack of 10)	(blank)
5005		
4036	Service Kit for Conti TG1B Renault	Conti Clamp-in TG1B Siemens VDO 433MHz Renault
5006		
4031	Service Kit for Conti TG1B PSA Ford	Conti Clamp-in TG1B Siemens VDO 433MHz PSA
5007		
4037	Service Kit for Conti TG1B black nut VW	Conti Clamp-in TG1B Siemens VDO 433MHz VW
5008		
4040	Service Kit for Conti TG1B Daimler	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
5014		
4026	Service Kit for Conti TG1B HKMC	Conti Clamp-in TG1B 433MHz HKMC
5015		
4038	Service Kit for Conti TG1B Daimler	Conti Clamp-in MB_no RF link Siemens VDO 433MHz Daimler
5016-10		
3039	Service Kit for SEL Gen 3.1 Nissan (Pack of 10)	Schrader Clamp-in Gen 2/3 Type fixed 20deg angle Hybrid Small Grommet Seal 433MHz Nissan
5017-10		
3011	Service Kit for SEL Gen-Alpha Aluminium rims Daimler Chrysler WAL (Pack of 10)	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
5018		
4035	Service Kit for Conti TG1C Renault	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
5020		
4019	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4065	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Suzuki
4021	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Ford
4070	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Volvo
4072	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Honda
4066	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz JLR
4071	Service Kit for Conti TG1C	Conti Clamp-in TG1C 433MHz Conti Nissan
4023	Service Kit for Conti TG1C	Conti Clamp-in TG1B 433MHz Ford
5021		
4027	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
4060	Service Kit for Conti TG1C HKMC	Conti Clamp-in TG1C 433MHz HKMC
5022		
4028	Service Kit for Conti TG1C Mazda	Conti Clamp-in TG1C 433MHz Mazda
5024-10		
3000	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford
3027	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
2020	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe
3068	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 315MHz Ford
1900	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3200	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3063	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
1920	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3078	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3086	Service kit Aluminium valve for SEL Snap-in Gen4 with valve (Pack of 10)	Schrader Snap-in Faraday 314.9MHz GM (China)
5025-10		
2020	Service kit Aluminium valve for SEL Snap-in Gen4 (5024-10 without valve, Pack of 10)	Schrader Clamp-in Fixed 20deg angle 433Mhz programmable WAL EZ-sensor® sensor Europe
5026-10		
3000	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
1900	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3063	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
1920	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3086	Valve for SEL Snap-in REV4 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 314.9MHz GM (China)
5028-10		
3005	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford
3027	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3068	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 315MHz Ford
1900	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz USA
3200	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3063	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
1920	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor® Snap-in 315/433 MHz APAC
3078	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3086	Valve for SEL Snap-in REV5 Gen4 - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 314.9MHz GM (China)
5029-10		
3008	Service Kit for SEL Gen-Alpha Chrysler FSK basic (Pack of 10)	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
5030-10		

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3053	Service Kit for SEL Gen-J GM (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM
3054	Service Kit for SEL Gen-J GM (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM
3055	Service Kit for SEL Gen-J GM (Pack of 10)	Schrader Clamp-in Gen J 433MHz GM
5033-10		
1210	HSS replacement valve with screw (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Snap-in 433 MHz Europe
3041	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Renault T4
3021	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Ford
3069	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Volvo
2210	HSS replacement valve with screw (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Clamp-in fixed angle 10° 433 MHz Europe
3023	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Ford
9014	HSS replacement valve with screw (Pack of 10)	Italsensor IT-100 snap-in
3076	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Subaru
3047	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz VW
3025	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
3029	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz GM
3044	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Volvo
3061	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz HKMC
3071	HSS replacement valve with screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
5037-10		
3033	Service Kit for SEL Gen Gamma GM (Pack of 10)	Schrader Clamp-in Gen Gamma 433MHz GM
5039		
9009	Service Kit for Huf/Beru valve length L=43mm Gen 2 Silver	Number reserved for Intellisens clamp-in
5050		
9009	Service Kit for Huf/Beru valve length L=43mm Gen 2 Black	Number reserved for Intellisens clamp-in
5056-10		
3013	Service Kit for SEL Gen Gamma Mercedes (Pack of 10)	Schrader Clamp-in Gen Gamma 433MHz Daimler
2200	Service Kit for SEL Gen Gamma Mercedes (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Clamp-in variable angle 433MHz Europe
3057	Service Kit for SEL Gen Gamma Mercedes (Pack of 10)	Schrader Clamp-in PAL Gen Delta 433MHz Daimler/BMW
9047	Service Kit for SEL Gen Gamma Mercedes (Pack of 10)	Italsensor IT-300 variable angle clamp-in

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
5057		
4032	Service Kit for Conti TG1C Renault / Nissan	Conti Clamp-in TG1C 433MHz Renault
5058		
4043	Service Kit for Conti TG1C BMW / Mini	Conti Clamp-in TG1C 433MHz BMW
5059		
4073	Service Kit for Conti TG1C Mitsubishi	Conti Clamp-in TG1C 433MHz Conti Mitsubishi
5060-10		
3009	Service Kit for SEL Gen Gamma Chrysler/Fiat (Pack of 10)	Schrader Clamp-in Gen Gamma 433MHz Chrysler/Fiat
5061-10		
1210	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Snap-in 433 MHz Europe
2000	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
3041	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Renault T4
3021	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Ford
3069	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz Volvo
2210	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Clamp-in fixed angle 10° 433 MHz Europe
3023	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Ford
9014	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Italsensor IT-100 snap-in
9005	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar sensor
9015	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Italsensor IT-200 clamp-in
3077	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
3094	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz GM
9024	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Mobis Snap-in Polysensor
9021	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for MW-Ital Clamp-in Sensor
9025	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Mobis Clamp-in Polysensor
9026	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar P&D2 20 degree
9027	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar P&D3 20 degree
9028	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar P&D1 10 degree
9029	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar P&D2 10 degree
9030	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar P&D3 10 degree
3076	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Subaru
3047	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz VW
9046	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Number reserved for Alcar sensor - ABS 10 degree

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3025	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
3029	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in HS with 20deg angle 433MHz GM
3044	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz Volvo
3061	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz HKMC
3071	Valve for SEL EZ-sensor@2.0 clamp-in 2210 part - includes mounting screw (Pack of 10)	Schrader Snap-in Faraday 433MHz GM
5062-10		
2000	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Schrader Clamp-in Fixed 10deg angle 433Mhz programmable WAL EZ-sensor@ sensor Europe
2210	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Clamp-in fixed angle 10° 433 MHz Europe
9005	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar sensor
3077	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford
3094	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz GM
9021	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for MW-Ital Clamp-in Sensor
9025	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Mobis Clamp-in Polysensor
9026	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar P&D2 20 degree
9027	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar P&D3 20 degree
9028	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar P&D1 10 degree
9029	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar P&D2 10 degree
9030	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar P&D3 10 degree
9046	Service Kit for SEL EZ-sensor@2.0 clamp-in 2210 part - without valve (Pack of 10)	Number reserved for Alcar sensor - ABS 10 degree
5063-10		
2200	Service Kit for SEL Gen Delta - without valve (Pack of 10)	Schrader programmable EZ-sensor@ 2.0 Clamp-in variable angle 433MHz Europe
3057	Service Kit for SEL Gen Delta - without valve (Pack of 10)	Schrader Clamp-in PAL Gen Delta 433MHz Daimler/BMW
9047	Service Kit for SEL Gen Delta - without valve (Pack of 10)	Italsensor IT-300 variable angle clamp-in
8001		
3011	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy / Steel rims 433MHz Daimler
3008	Aluminium valve stem for SEL Gen-Alpha without plastic cap	Schrader Clamp-in Gen Alpha for Alloy rims 433MHz Chrysler
8002-10		
4035	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C Siemens VDO 433MHz Renault
4032	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Renault
4027	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz HKMC
4021	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Ford
4060	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz HKMC
4018	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Jeep FCA
8003-10		
4019	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Ford
4065	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Suzuki
4028	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz Mazda
4043	Aluminium valve stem for Conti TG1C with plastic cap (Pack of 10)	Conti Clamp-in TG1C 433MHz BMW

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
8004-10		
3000	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA
3001	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz PSA HP
3005	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3007	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Chrysler
3020	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ford
3027	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3049	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3056	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz HKMC
3062	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz GM
3068	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Ssangyong WAL
3018	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 315MHz Ford
3200	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 315Mhz Programmable NON-WAL EZ-sensor® USA (Was 1200)
3210	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433Mhz programmable WAL EZ-sensor® USA (Was 1210)
3078	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz Great Wall (China)
3024	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Clamp-in Fixed 20deg angle 433MHz Ford
3048	T10 Screw for Snap-in sensor valve REV4/REV5 (Pack of 10)	Schrader Snap-in GEN4 type 433MHz VW
5034-10		
9024	HKMC Hybrid Rev4.5 Snap In Valve & Screw Assy (Pack of 10)	Number reserved for Mobis Snap-in Polysensor
5061B-10		
1210	Black valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader programmable EZ-sensor® 2.0 Snap-in 433 MHz Europe
2210	Black valve for SEL EZ-sensor®2.0 clamp-in 2210 part - includes mounting screw	Schrader programmable EZ-sensor® 2.0 Clamp-in fixed angle 10° 433 MHz Europe
5067		
9014	Snap in service kit italsensor	Italsensor IT-100 snap-in
5068		
9015	clamp in service kit italsensor	Italsensor IT-200 clamp-in
5070		
9015	clamp in service kit italsensor	Italsensor IT-200 clamp-in
5076-10		
2200	EZ-Sensor Delta Service Kit	Schrader programmable EZ-sensor® 2.0 Clamp-in variable angle 433MHz Europe
8006-2000		
1210	HSS screw (Pack of 2000)	Schrader programmable EZ-sensor® 2.0 Snap-in 433 MHz Europe
3041	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz Renault
3002	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz PSA
3003	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz PSA HP
3064	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz Subaru
3059	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3060	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz HKMC
3012	HSS screw (Pack of 2000)	Schrader Snap-in HS with 10deg angle 433MHz Daimler
3073	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Renault T4
3021	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Ford
3069	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz Volvo
3023	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Ford
3077	HSS screw (Pack of 2000)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz Ford

Service Kits Part Nr. Schrader Part Number (NEW)	Service Kit Description	Sensor Description
3094	HSS screw (Pack of 2000)	Schrader Faraday Clamp-in Fixed 20deg angle 433MHz GM
3076	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Subaru
3047	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz VW
3025	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz GM
3029	HSS screw (Pack of 2000)	Schrader Snap-in HS with 20deg angle 433MHz GM
3044	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz Volvo
3061	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz HKMC
3071	HSS screw (Pack of 2000)	Schrader Snap-in Faraday 433MHz GM