

## VKMA 01250

## Technical Bulletin - November 2011



AUDI, FORD, SEAT, SKODA, VW



Kit content evolution: Addition of 2 studs in the kit.



OE #: 038 198 119 A, 038 198 119 C

CAR MAKER	MODEL	ENGINE
AUDI	A2, A3, A4, A6	1.4 Tdi, 1.9 Tdi, 2.0 Tdi
FORD	Galaxy	1.9 Tdi
SEAT	Arosa, Cordoba, Ibiza, Alhambra, Altea, Leon, Toledo	1.4 Tdi, 1.9 Tdi, 2.0 Tdi
SKODA	Fabia, Praktik, Octavia , Roomster, Superb	1.4 Tdi, 1.9 Tdi, 2.0 Tdi
VW	Golf Plus, Passat, Polo, Sharan, Touran, Transporter	1.4 Tdi , 1.9 Tdi, 2.0 Sdi, 2.0 Tdi

For detailed applications, please refer to the latest SKF catalogue.

In line with SKF's philosophy to offer a complete repair solution for the installer, SKF has included an additional 2 studs in the VKMA 01250 kit.



As with all fastening products included into SKF kits, the studs and the nuts should be changed at the same time to avoid excessive stud elongation during the re-torquing process and any potential for timing system failure.


## Two new stud components in the VKMA 01250 kit:








To perform a safe and professional repair; all of the required fastening components are included in this kit, along with the specific fitting instructions which contain all available technical information.





## The 2 studs have been added to the following SKF kits: VKMA 01250, VKMC 01250-1, VKMC 01250-2 and VKMC 01250-3

® SKF is a registered trademark of the SKF Group.

© SKF Group 2011

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

