

## Engineered to perform, guaranteed to last

## MEYLE-HD ball joints for the Renault Trafic III, Renault Master II, Opel Movano A and Nissan Interstar (X70)

Continuously heavy axle loads are a frequent cause of early ball joint failure on Renault vans: Suffering from undersizing, original parts tend to fail quickly under the demanding operating conditions. Technically refined MEYLE-HD ball joints for Renault vans excel through the following product features:

- Use of extremely wear-resistant plastic socket in the ball joint
- Constant lubrication film between the ball pin and plastic socket
- High-strength self-locking nut
- MEYLE high-tech grease field-tested in shipbuilding and wind energy R&D
- High-quality rubber sleeve featuring a blue clamp ring



(Short no. MBJ0105HD)



MEYLE no. 616 010 0005/HD (Short no. MBJ0271HD)