



Chain tensioner for timing chains, with housing and fitting materials

to fit

Mercedes-Benz A-Class W169 A150, A160, A170, A180, A200 Mercedes-Benz B-Class W245 B150, B160, B170, B180, B200

PROBLEM

Missing fitting materials and mountings are a widespread problem. Searching for and procuring the individual components costs time and money.

CAUSE

The manufacturer recommends the replacement of all fitting materials when changing the chain tensioner SWAG 10 93 0548.

SOLUTION

febi bilstein provides the complete solution under a single part number. SWAG 10 10 0410 is a complete set, containing six individual components in total, with all the parts required for a professional repair.

ATTENTION

Replace the gasket and clean the sealing face. Tighten the M6 bolts with 8 Nm torque.



SWAG no. 10 10 0410

Repl. no. 266 050 02 11 S3

1x Chain tensioner • 1x Gasket • 2x M6 bolt 1x Sump plug • 1x Gasket ring

Register now for the official SWAG newsletter and receive the latest technical information automatically by email!

Further information may be obtained at: partsfinder.bilsteingroup.com