



Service Info



Timing belt kit 530 0536 10

Manufacturer: Lada

Models: Kalina
Priora

Engines: 1.4 16V, 1.6, 1.6 16V

Part no.: 530 0536 10



Image 1: 530 0536 10 — INA repair set for the timing belt drive

In addition to individual deflection pulleys, Schaeffler Automotive Aftermarket is now offering a complete timing belt kit for the models specified above. This set comprises tensioner pulley 531 0841 10 together with the corresponding bolt, deflection pulley 532 0604 10, and the timing belt.

The tensioner pulley and timing belt must always be installed together as a single unit. It is not permitted to use mixed components when installing these parts.

Note the specifications of the vehicle manufacturer!

The components, which are specially tailored to one another, ensure that the timing belt is optimally tensioned in all engine operating conditions and at all engine temperatures.

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
info@luk-as.co.uk
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

