



Service Info



Design change

affecting tensioning pulley 531 0572 10

Manufacturers: Citroën, Fiat, Peugeot

Model:

Citroën: Berlingo, C2, C3, Nemo, Saxo, Xsara

Fiat: Fiorino, Qubo

Peugeot: 106, 206, 207, 306, 307, 1007, Partner

Engine: 1.1, 1.4

Part no.: 531 0572 10

OE number:

Citroën: 0829.90

Fiat: 9642929880

Peugeot: 0829.90



Figure 1: Previous design

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 531 0572 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.



Figure 2: New design

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

info@luk-as.co.uk

www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

