



INA Service Info



Rocker arm 422 0246 10

Replaces several designs

Manufacturer: BMW

Models: 1', 2', 3', 4', 5', 6', 7',
X1, X3, X4, X5, X6,
Mini

Engines: B 47, N 47, M57, N 57, 9HZ

Part no.: 422 0246 10 (new)
422 0230 10 (replaced)
422 0117 10 (replaced)
422 0096 10 (replaced)

For current listing refer to catalogue media



Photo: Left - old design, right - new design

Schaeffler Automotive Aftermarket is offering a new rocker arm for the engines listed. It replaces all previous designs.

It meets all technical specifications and differs from the previous versions only in appearance.

Old and new versions can always be used together without any problem.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT